USB4 1.0 ENGINEERING CHANGE NOTICE FORM

Title: Change C3S Bit Polarity

Applied to: USB4 Specification Version 1.0						
Brief description of the functional changes:						
Changes the polarity of the Connection Manager TBT3 Support bit.						
Benefits as a result of the changes:						
Current Connection Managers don't set this bit, even though TBT3-compatibilty is supported. Changing the polarity will help support the current eco-system.						
An assessment of the impact to the existing revision and systems that currently conform to the USB specification:						
None						
An analysis of the hardware implications:						
None						
An analysis of the software implications:						
None						
An analysis of the compliance testing implications:						
None						

USB4 1.0 ENGINEERING CHANGE NOTICE FORM

Actual Change

(a). Table 8-3, Router Configuration Space Basic Attributes, Page 278

From Text:

5	ROUTER_CS_5	23	CM TBT3 Support (C3S)	R/W	0b
			This bit identifies if a USB4 Connection Manager is TBT3-Compatible:		
			0b - Not TBT3-Compatible		
			1b – TBT3-Compatible		
			A TBT3 Connection Manager does not write to this bit.		
			A Router shall ignore this bit if the <i>Configuration Valid</i> bit is set to 0b.		

To Text:

5	ROUTER_CS_5	23	CM TBT3 Not Supported (C3NS)	R/W	0b
			This bit identifies if a USB4 Connection Manager is TBT3-Compatible:		
			<u>1</u> 0b − Not TBT3-Compatible		
			<u>0</u> 1 b – TBT3-Compatible		
			A TBT3 Connection Manager does not write to this bit.		
			A Router shall ignore this bit if the <i>Configuration Valid</i> bit is set to 0b.		
			This field does not apply to Host Routers.		