## **USB4 1.0 ENGINEERING CHANGE NOTICE FORM**

**Title: DP Resource De-Allocation Applied to: USB4 Specification Version 1.0** 

Brief description of the functional changes:		
A De-Allocate DP Resource Operation to a DP IN Adapter without any allocation should end successfully.		
Benefits as a result of the changes:		
More robust definition of the feature.		
An assessment of the impact to the existing revision and systems that currently conform to		
the USB specification:		
None		
An analysis of the hardware implications:		
None		
An analysis of the software implications:		
None		
An analysis of the compliance testing implications:		
None		

## **USB4 1.0 ENGINEERING CHANGE NOTICE FORM**

## **Actual Change**

## (a). Table 8-28

Table 8-28. De-Allocate DP Resource Completion Metadata and Status

Field	Bit(s)	Description
Metadata	31:0	DisplayPort Number This field contains the DisplayPort Number value from the Operation Metadata.
Status	29:24	Status  Oh: Resource was de-allocated  1h: Resource was not de-allocated  2h - Fh: Reserved  If no resource is allocated to this DP IN Adapter, then a Router shall respond with Status = 0h.