## Project 10571EZ: Cranberry Rake Box

Even though much of the commercial cranberry crop is harvested by machine, the old-fashioned cranberry rake is still used to some extent. This miniature version of the cranberry rake is ideal for displaying dried flowers or for




storing some small odds and ends. A small hole bored through the back enables it to be hung on a wall. The tines are made from birch dowel stock, while the remaining parts are made from pine.

## **Cranberry Rake Box Materials List**

Part	Description	Size	No. Req'd	
А	Side	3/8" x 3" x 5-5/8"	2	
В	Front	3/8" x 2-1/8" x 6-1/8"	1	
С	Back	1/2" x 2-1/2" x 5-3/8"	1	
D	Bottom	3/8" x 3-3/8" x 6-1/8"	1	
Е	Tine	1/4" dia. x 3-1/2" long	8	
F	Handle	1/2" x 3/4" x 5-1/2"	1	

## **Cranberry Rake Box Complete Schematic**



## Cranberry Rake Box Step-by-Step Instructions

- 1. Hand plane thicker stock to obtain the 3/8" thickness for the two sides (A).
- 2. Cut the stock to a width of 3" and a length of 5-5/8".
- 3. Transfer the grid pattern from the drawing to the stock.
- 4. Cut out on the band or jig saw, staying just outside the marked line.
- 5. Sand exactly to the line.
- 6. Cut the front (B) and the bottom (D) to the correct dimensions from 3/8" thick stock.
- 7. Cut 1/2" thick stock to length and width to make the back (C).
- 8. Lay out and mark the location of the 1/4" diameter by 3/8" deep holes to accept the tines (E).
- 9. Cut the tines to a length of 3-1/2".
- 10. Glue the tines into place.
- 11. Allow the glue to dry.
- 12. Clamp the back in a vise.
- 13. Use a belt sander to bevel the end of each tine.
- 14. Make the handle as shown.
- 15. Attach the handle to the front with glue and a pair of finishing nails driven from the back side.
- 16. Assemble the front, back, sides, and bottom with glue and countersunk finishing nails.
- 17. Fill the countersunk holes and sand smooth.
- 18. Final sand all parts before staining.
- 19. Allow the stain to dry thoroughly.
- 20. Apply two coats of a penetrating oil.

These plans were originally published in Volume 10, Issue 5 of *The Woodworker's Journal* (Sept./Oct. 1986, page 52).