


ARDOR / BUILD ONLY WHAT YOU NEED

M1 — Five complete boards. Each needs only an external source/host and its listed regulated supply.



No carrier or other Ardor module required. Separate PCBA setups repeat costs; build a subset for best economy.