
Revision Date Author		Author	Description		
1	13/05/2017	G.Boschini	First Draft		
2	26/08/2017	G.Boschini	- Updated symbol from library - Removed micro SD card interface - Removed Artik (20 USD bebug - Removed Artik (20 USD bebug - Removed MCSL diagnometor - Removed MCSL diagnometor - Removed Accelerometer and Gyroscope sensor - Changed color led *SY and *SYS - Changed Display and Camera connector - Changed MIFI*SL Module - Changed LED driver functionality (from CM3 or Artik) - Moved on IZCO Camera, Display and EEPROM HAT - MOVED CAMERA - MOVED CAM		
3	20/11/2017	G.Boschini	- Updated symbol from library - Removed DSMI - Added DSMI - Removed DSMI - Added DSMI - Added DSMI - Removed DSMI - Added DSMI - Removed DSMI - Added DSMI - Removed DSMI - Removed DSMI - Removed Capacitor at DC input of mPCIB - Improved capacitor at DC input of mPCIB - Changed MAT Uses to 3A - Changed MAT Uses to 3A - Changed Pullbown LED RGB Resistor - Changed Voltage Input Rail up to 30V		
4	02/01/2018	G.Boschini	- Correct PCB Led SilkScreen		
5	17/01/2018	G.Boschini	- Removed UART Bluetooth connection - Changed IZC bus for RTC, Artik 020, CM3, IO Expander and isolated RTC and Artik bus from IO Expander and CM3 when CM3 is not powered - Modified SV HAT Fower Supply - Enable Modified To Hat Fower Supply - Enable Modified To Hat Fower Supply - Rable Modified To Hat Fower Supply - Removed MiFi clock enable - Added Supply - Removed SGB Led - Added serial connection from CM3 to Artik - Added SWO connection from CM3 to Artik - Added SWO connection from CM3 to Artik - Added SWD Connection from CM3 to Artik - Moved BUMI Enable and PSW MiFit to IO Expander - Replaced power input connector with black version		
6	06/02/2018	G.Boschini	- Updated symbol from library - Corrected SW-I2C net name - Added RGB Led - Removed SWO connection from CM3 to Artik - Moved SWO connection from CM3 to Expander		
7	22/02/2018	G.Boschini	- Removed logo from silkscreen		
8	17/05/2018	G.Boschini	- Added FIN logo on silkscreen - Changed value of R259,R264,C218,C219,C222,C224,C227,C228,C229,C230		
9	10/12/2018	G.Boschini	- Removed Reset Button (PB1) - Removed protection networks of HAT connector (DS11,DS12,DS13,DS14,DS15,DS16,DS17,DS15,DS16,DS15,DS16,DS15,DS16,DS15,DS16,DS15,DS16,DS15,DS16,DS15,DS16,DS15,DS16,DS15,DS16,DS16,DS16,DS16,DS16,DS16,DS16,DS16		
10	31/01/2019	G.Boschini	- Updated symbol from library - Replace LAM9914 with industrial version - Replace LAM9 connector with temperature extended version - Added power supply from debug USS - Added R311 for reset MCU - Change to mount USB strip connector		
11	04/08/2020	M. Cossali	- Changed R116 and R32 to 1k		







	Project	BALENA FIN	Page name	
la alla na Pira	Board	BALENA FIN	00 - REVISION	
balenaFin	Design	er G.Boschini	Approved Approved	
	Project	Code 2017-3009	Customer BALENA.IO	
	Interna	Code -	Code -	
Data		Rev. changes		
Tuesday, August 04, 2020	11	See Revision Page		1/11
-			•	

