

DeLorean Midwest

990 Lutter Drive
Crystal Lake, IL 60014

Phone # (815) 459-6439 suzy@deloreanmw.com
Fax # 815 459 1675 deloreanmidwest.com

Bill To

Alex Menkes

Service Invoice**Date**

11/1/2025

Invoice #

17800

VIN

8BD001517

Stock

1350

Key Code**BRP Date****Mileage in**

23314.7

Item Code	Description	Qty	Amount
	CUSTOMER NOTE: Last ran 5 years ago - ALL FLUIDS DRAINED other shop was halfway through a hose kit and gave up		
1016	Visual Inspection of Current work done, Some done by another shop NOTE Some parts removed /Left Loose (-Airbox - Heatsheild - All 6 Spark Plugs removed - New Starter installed) *Diag /Repair No Crank No Start NOTE: w/Power Probe Whi/Red has no 12v @ relay socket - check spark and power - found starter circuit not complete	2	480.00
37407	PERFORM STARTER WIRING MOD RECALL	1	240.00
114017	STARTER MOD WIRE	1	12.06T
34109	R&R SPARK PLUGS- SET OF 6	1	480.00
34112	PERFORM COMPRESSION TEST - (1:155, 2:increase to 80, 3:increase to 130, 4:165, 5:165, 6:165) - new plugs installed and run engine to see if improves	1	240.00
102443A	SPARK PLUG, NGK	6	23.88T
	SUBTOTAL LINE		1,475.94
1011	DIAGNOSTIC TIME TO CHECK COLD WARM UP SYSTEM - NOTE: WUR Cleaned out on Car	1	408.00
21010	PERFORM FUEL PRESSURE AND REST TEST	1	288.00
82101	R&R FUEL PUMP ACCESS COVER PANEL	1	96.00
21013	CLEAN OUT TANK IN CAR	1	480.00
21014	INSTALL OEM FUEL PUMP KIT	1	960.00
	REBUILD ORIGINAL STYLE FUEL PUMP (INTEGRATED UNAVAILABLE)		
101391	BOOT, FUEL PUMP	1	49.99T
101643A	SCREEN, FUEL PUMP	1	5.97T
105020	LINE, FUEL RETURN	1	24.95T
106286	HOSE, FUEL RETURN (OG STYLE FP)	1	19.69T
106287	HOSE, FUEL PICK UP (OG STYLE FP)	1	15.95T
106684	SEAL, FUEL PUMP COVER	1	34.99T
110085A	FUEL PUMP, ORIGINAL STYLE - REPRO	1	99.00T

DeLorean Midwest

990 Lutter Drive
Crystal Lake, IL 60014

Phone # (815) 459-6439 suzy@deloreanmw.com
Fax # 815 459 1675 deloreanmidwest.com

Bill To

Alex Menkes

Service Invoice**Date**

11/1/2025

Invoice #

17800

VIN

8BD001517

Stock

1350

Key Code**BRP Date****Mileage in**

23314.7

Item Code	Description	Qty	Amount
106740	HARNESS, FUEL PUMP	1	18.99T
106977	WASHER M12 SEAL	1	0.49T
106979A	HOSE, FUEL FEED 19"	2	15.00T
100523	FILTER, FUEL w/Seal & Pad	1	17.58T
110589	NUT, DOMED	1	11.67T
SP10830	CLAMP, HOSE	1	0.49T
SP10345	CLAMP, HOSE FUEL LINE 12M	4	5.40T
SP10349	CLAMP, HOSE	1	0.73T
SP10356	CLAMP, PUMP SUPT HOSE CLIP	1	2.56T
SP10388	CLAMP, FUEL PUMP SEAL	1	1.29T
SP10728	CLIP EDGE	1	1.31T
1016	*R&R New Satinless feed line Y NOTE: Bench Job Installed on new Fuel Filter	0.1	24.00
102365A	MAIN FUEL FEED LINE (BRAIDED STAINLESS)	1	94.56T
USEDMISC	FUEL PUMP BAFFLES MISSING - GOOD USED PARTS INSTALLED 110043, 106241, 108683, 108905	1	10.00T
110555	SENDER, FUEL	1	110.55T
102365A	MAIN FUEL LINE - FUEL FLT TO FUEL DIS. (BRAIDED STAINLESS)	1	94.56T
37408	*WIRE REPAIR - CAR SIDE OF FP HARNESS NOTE: GROUND WIRE FOUND CUT OUT WITH NEW WIRE RAN - REPAIR 2 WIRE SHELL POWER/GROUND	1	240.00
21005	ORIGINAL ACCUMULATOR & LINES DETERIORATED		
100519	*R&R FUEL ACCUMULATOR & PAD	1	360.00
106997	*ACCUMULATOR, FUEL w/ PAD	1	349.99T
106997	*HOSE, ACCUMULATOR RETURN (12")	1	7.95T
106999	*HOSE, ACCUM FEED (19")	1	6.94T
SP10345	*CLAMP, HOSE FUEL LINE 12M	2	2.70T
SP10348	*CLAMP, HOSE FUEL / COOLANT	2	1.46T
GASOLINE	GASOLINE FOR CHECK OUT (tax paid)	5	23.40

DeLorean Midwest

990 Lutter Drive
Crystal Lake, IL 60014

Phone # (815) 459-6439 suzy@deloreanmw.com
Fax # 815 459 1675 deloreanmidwest.com

Bill To

Alex Menkes

Service Invoice**Date**

11/1/2025

Invoice #

17800

VIN

8BD001517

Stock

1350

Key Code**BRP Date****Mileage in**

23314.7

Item Code	Description	Qty	Amount
21023	FLUSH ALL FUEL LINES WITH FILTER AND ACCUMULATOR REMOVED (typical of system restoration)	1	240.00
22007	LIFT INJECTOR NOZZLE AND/OR SEAL, ALL SIX, PERFORM FLOW AND BALANCE TEST	1	624.00
22005	R&R Injector Nozzle x2 Y NOTE: #1, #2 Poor Flow - Bench Cleaned and still failed - Replaced	2	528.00
102742	INJECTOR NOZZLE	2	149.26T
102631	SEAL, INJECTOR	2	6.26T
102346	CLIP, INJECTOR	2	6.38T
22012	R&R FUEL DISTRIBUTOR	1	264.00
22018	REBUILD FUEL DISTRIBUTOR (BENCH JOB)	1	695.00
102855	O-RING,FUEL DIST BASE	1	2.56T
31001	REPLACE BATTERY AND INSTALL KNIFE SWITCH CUTOFF	1	48.00
78V-PG	BATTERY - AC Delco PREMIUM 78GHR	1	179.59T
Z25009a	Battery Cutoff - Knife Switch	1	23.95T
1010	LOF	1	120.00
102114B	OIL FILTER w/102101 seal	1	7.50T
W100559	ENGINE OIL CASTROL 20W50	7	41.93T
	total make run items		6,820.59
	SUBTOTAL LINE		6,820.59
	LARGE COOLING SYSTEM LEAK DISCOVERED ON FIRST FILL		
14101	*R&R THROTTLE HOUSING- AIRFLOW CONTROL UNIT	1	408.00
14103	*R&R INTAKE MANIFOLD, REPLACE 'O' RINGS	1	360.00
13002	*R&R WATER PUMP	1	360.00
14109	*CLEAN OUT ENGINE VALLEY & REPLACE HOSES	1	120.00
71310	*R&R WATER RETURN PIPE	1	72.00
1016	*TORCH WORK - FROZEN W/P BOLTS x3 Y	0.5	120.00
1016	*BROKEN BOLT REMOVAL - DRILL OUT / TAP TO SAVE HOLE N	0.5	120.00
1016	*INSTALL TIME SERT Y NOTE: W/P HOLE REPAIRED	0.4	96.00
1016	*TORCH WORK - FROZEN Y-PIPE BOLTS x3 Y	0.5	120.00
1016	*DIAG Water Leak in Valley Y NOTE: w/ Pressure gauges	0.5	120.00

DeLorean Midwest

990 Lutter Drive
Crystal Lake, IL 60014

Phone # (815) 459-6439 suzy@deloreanmw.com
Fax # 815 459 1675 deloreanmidwest.com

Bill To

Alex Menkes

Service Invoice**Date**

11/1/2025

Invoice #

17800

VIN

8BD001517

Stock

1350

Key Code**BRP Date****Mileage in**

23314.7

Item Code	Description	Qty	Amount
102119	*WATER PUMP w/ GASKET	1	214.16T
102139	*BOLT, WATER PUMP BACK M7 (STAINLESS)	5	6.80T
102709	*THERMOSTAT	1	21.91T
102156	*GASKET, THERMOSTAT	1	1.95T
106786	*BLEED ADAPTOR	1	24.94T
102153	*HOSE, WATER PUMP UPPER L+R	2	9.48T
102149	*HOSE, WATERPUMP	1	3.29T
102481	*HOSE, HEATER PIPE	1	1.20T
101754	*HOSE, HEATER	2	2.44T
102482	*PIPE, COOLANT REPRO	1	29.82T
SP10349	*CLAMP, HOSE	5	3.65T
SP10352	*CLAMP, HOSE	4	2.92T
SP10353	*CLAMP, HOSE	2	1.46T
13005	*R&R WATER DISTRIBUTION PIPE AND/OR SEALS	1	288.00
13020	*SUBLET MACHINE RECONDITION WATER DISTRIBUTION PIPE	1	45.00
13021	*SWAP SENSORS TO EXCHANGE Y-PIPE NOTE: BENCH TEST VAC 3PORT SWITCH - PASS	1	72.00
71303	*R&R HOT WATER VALVE AND SHORT HOSE	1	120.00
100763A	*VALVE, HOT WATER	1	18.88T
101760	*BLEED HOSE, - REPLACED NOW WITH BETTER ACCES BEFORE INTAKE IS REINSTALLED	1	9.21T
101759	*HOSE, HEATER - REPLACED NOW WITH BETTER ACCES BEFORE INTAKE IS REINSTALLED	1	11.56T
SP10348	*CLAMP, HOSE FUEL / COOLANT	2	1.46T
SP10349	*CLAMP, HOSE	1	0.73T
SP10350	*CLAMP, HOSE	1	0.73T
13012	*R&R ENGINE BLOCK DRAINS DURING SERVICE	1	120.00
13009	*BLEED COOLING SYSTEM AFTER REPAIR (ENG AT IDLE, COMPLETE 2 FAN CYCLES & CHECK HEATER OPERATION - INCLUDES CHECKING COOLING FANS FOR OPERATION AND DIRECTION OF ROTATION)	1	288.00
K111171	*INTAKE O-RING KIT	1	11.22T
72106	BOTH BELTS DETERIORATED (A/M GM ALT) *R&R BELTS, ALTERNATOR AND A/C	1	192.00

DeLorean Midwest990 Lutter Drive
Crystal Lake, IL 60014

Phone # (815) 459-6439

Fax # 815 459 1675

suzy@deloreanmw.com

deloreanmidwest.com

Service Invoice**Date**

11/1/2025

Invoice #

17800

VIN

8BD001517

Stock

1350

Key Code**BRP Date****Mileage in**

23314.7

Bill To

Alex Menkes

Item Code	Description	Qty	Amount
102442	*DRIVE BELT, ALTERNATOR	1	21.35T
105505	*DRIVE BELT, A/C	1	14.69T
	SUBTOTAL LINE		3,434.85
1012	COMPLETE CHECK OUT AND PREPARE DETAILED ESTIMATE OF REQUIRED REPAIR ITEMS NEEDED	1	525.00
W100564	SHOP SUPPLIES & ENVIRONMENTAL DISPOSAL		251.66T
	Sales Tax-McHenry		180.51

The only warranty applicable to the part(s) on this order are those which may be offered by the manufacturer or supplier. DMC expressly disclaims all warranties, either expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) or service. The buyer shall not be entitled to recover from DMC any consequential damages, damages to property, damages for loss of use, loss of profits, or income or any other incidental damages.

Total \$12,688.55**Payments/Credits** -\$5,198.00**Balance Due** \$7,490.55