PRAMANA / INSPECTION RECORD

DT-07 is not roadworthy

Unit: DT-07 · B 9123 KD | Inspector: Budi | Location: Tanjung Enim

Submitted: 29 Oct 2026, 07:42 WIB | Report: LI-2026-10-29-DT07

Plan: P2H · U-type dump truck

Good: 6 | Not good: 2 | Unable to inspect: 0 | STOP: 2

1. Cabin & safety equipment

Good

Checked; no abnormality observed.



Fire extinguisher label close-up

2. Brakes & air system

Good

Checked; no abnormality observed.



DT-07 left side

3. Tyres & wheel nuts

Not good / STOP

Approximately 6 cm bulge on the left rear tyre sidewall.



DT-07 tyre sidewall bulge

4. Dump body

Good

Checked; no abnormality observed.



DT-07 left side

5. Hydraulic cylinder

Good

Checked; no abnormality observed.



DT-07 left side

6. Body safety prop

Good

Checked; no abnormality observed.



DT-07 left side

7. Tailgate & latch

Good

Checked; no abnormality observed.



DT-07 left side

8. Lights & reflectors

Not good / STOP

Left brake light does not illuminate during the functional check.



DT-07 left side