DEMO-1 is not roadworthy

Unit: DEMO-1 · B 9101 KD | Inspector: Alex | Location: Tanjung Enim

Submitted: 7 Nov 2026, 11:22 WIB | Report: LI-ee9abbcb-7a1d-470a-beb0-d716984c73db

Plan: P2H · U-type dump truck

Good: 0 | Not good: 1 | Unable to inspect: 7 | STOP: 8

1. Cabin & safety equipment

Unable to inspect / STOP

Alex reports safe access and qualified functional testing are unavailable and requests STOP pending safe reinspection. Photo shows a bracket-mounted extinguisher, a visible seat belt and an inspection tag marked expiry 03/2027; pressure gauge reading is not established. Seat belt and horn functionality and all mirror checks remain unverified. No functionality inferred from photo.

Reason: Safe access and qualified functional testing unavailable.



Red fire extinguisher held in a cabin bracket beside a seat; a seat belt is visible. Yellow inspection tag reads location CAB and expiry 03/2027. Pressure gauge reading is not established from this view. Photo does not demonstrate seat belt or horn functionality or establish all mirror checks.

2. Brakes & air system

Unable to inspect / STOP

Alex reports safe access and qualified functional testing are unavailable and requests STOP pending safe reinspection. Photo shows a wide exterior view of a yellow dump truck; brake components and air-pressure gauges are not visible in sufficient detail. Air pressure, leaks, parking brake and service brake response remain unverified; no functionality inferred from photo.

Reason: Safe access and qualified functional testing unavailable.



Wide exterior view of a yellow dump truck on a quarry road. Brake components and air-pressure gauges are not shown in sufficient detail to assess condition; this photo does not establish air pressure, absence of leaks, or parking and service brake functionality.

3. Tyres & wheel nuts

Not good / STOP

Photo shows a pronounced tyre sidewall bulge with surrounding cracking, meeting the tyre STOP condition. Alex also reports the bulge and requests STOP; vehicle must not operate. Only part of this tyre and rim is visible; wheel nuts and remaining tyres on both sides remain unverified.



Close-up of a dirty heavy-vehicle tyre with a pronounced outward sidewall bulge and visible cracking around the bulged area. Only part of the tyre and rim is shown; wheel nuts and all other tyres are not established by this view.

4. Dump body

Unable to inspect / STOP

Alex reports safe access and qualified functional testing are unavailable and requests STOP pending safe reinspection. Photo shows a yellow dump truck with its body lowered, aggregate above the side wall, and dirt and surface marks on the visible body side. Body floor, welds and mounting points are not visible in sufficient detail to assess structural cracks, deformation or loose mountings; no functionality or structural soundness inferred.

Reason: Safe access and qualified testing unavailable.



Wide exterior view of a yellow dump truck with its body lowered and aggregate visible above the side wall. The visible body side has dirt and surface marks. Body floor, welds and mounting points are not shown in sufficient detail to establish absence of structural cracks, deformation or loose mountings.

5. Hydraulic cylinder

Unable to inspect / STOP

Alex reports safe access and qualified functional testing are unavailable and requests STOP pending safe reinspection. Photo shows a yellow dump truck with its body lowered and aggregate above the sides. The hydraulic cylinder, hoses, couplings and seals are not visible in sufficient detail to assess damage or leakage. Hydraulic condition and functionality remain unverified; no functionality inferred from photo.

Reason: Safe access and qualified functional testing unavailable.



Wide exterior view of a yellow dump truck with its dump body lowered and aggregate visible above the sides. The hydraulic cylinder, hydraulic hoses, couplings and seals are not shown in sufficient detail to assess damage or leakage; hydraulic function is not demonstrated.

6. Body safety prop

Unable to inspect / STOP

Alex reports safe access and qualified functional testing are unavailable and requests STOP pending safe reinspection. Photo shows a yellow dump truck with its body lowered and aggregate above its sides. The mechanical body safety prop is not clearly visible; its presence, condition and engagement remain unverified. No functionality or absence of the prop inferred from the photo.

Reason: Safe access and qualified functional testing unavailable.



Wide exterior view of a yellow dump truck at a quarry with the dump body lowered and aggregate visible above its sides. The mechanical body safety prop is not clearly visible; its presence, condition and engagement cannot be established from this image.

7. Tailgate & latch

Unable to inspect / STOP

Alex reports safe access and qualified functional testing are unavailable and requests STOP pending safe reinspection. Photo shows a front-left exterior view of a yellow dump truck with its body lowered and aggregate above the sides. Rear tailgate, hinges, locking pins and latch are not shown in sufficient detail to assess condition or secure engagement. Closing and locking functionality remain unverified; no functionality inferred from the photo.

Reason: Safe access and qualified functional testing unavailable.



Wide front-left exterior view of a yellow dump truck at a quarry, with its body lowered and aggregate above the sides. The rear tailgate, hinges, locking pins and latch are not shown in sufficient detail to assess their condition or secure engagement. The photo does not demonstrate tailgate closing or locking functionality.

8. Lights & reflectors

Unable to inspect / STOP

Alex reports safe access and qualified functional testing are unavailable and requests STOP pending safe reinspection. Photo shows a front-left view of a yellow dump truck with its body lowered; a front lamp assembly and roof marker lamps are visible, but operation is not demonstrated. Rear brake lights and the full set of indicators and reflectors are not sufficiently shown. Headlight, brake light and indicator operation and reflector condition remain unverified; no functionality inferred from photo.

Reason: Safe access and qualified functional testing unavailable.



Wide front-left view of a yellow dump truck at a quarry with its body lowered. A front lamp assembly and roof marker lamps are visible, but illumination and operation are not demonstrated. Rear brake lights and the full set of indicators and reflectors are not shown sufficiently to assess their condition or functionality.