DEMO-2 is not roadworthy

Unit: DEMO-2 · B 9102 KD | Inspector: Alex | Location: Tanjung Enim

Submitted: 7 Nov 2026, 11:25 WIB | Report: LI-dfcb81e2-232f-4eca-8dad-12f0d16da30b

Plan: Demo 2 · Spec inspection

Good: 0 | Not good: 1 | Unable to inspect: 7 | STOP: 8

1. Cabin and safety equipment

Unable to inspect / STOP

Alex reports safe access and qualified functional testing are unavailable and requests STOP pending safe reinspection. Available photo shows a mounted extinguisher with tag EXPIRES 03/2027 and DATE 03/12/2024; pressure gauge indication is not visible. Seat, belt webbing and steering wheel are visible, but belt, horn, reversing alarm and steering functionality and complete mirror/windscreen condition remain unverified. No functionality inferred; cabin safety cannot be safely completed.

Reason: Safe access and testing unavailable.



Red fire extinguisher secured in a bracket inside the cabin. Yellow inspection tag visibly reads EXPIRES 03/2027 and DATE 03/12/2024. Pressure gauge indication is not visible. Seat, belt webbing and steering wheel are visible; the image does not establish belt, horn, reversing alarm or steering function, or complete mirror and windscreen condition.

2. Brakes and air system

Unable to inspect / STOP

Alex reports safe access and qualified functional testing are unavailable and requests STOP pending safe reinspection. Available photo shows an exterior front-left view of a yellow dump truck; air-pressure gauge and brake components are not visible. Normal pressure build-up, absence of audible air leaks and parking-brake holding ability remain unverified; no functionality inferred.

Reason: Safe access and testing unavailable.



Exterior front-left view of a yellow Mack dump truck at a quarry. The air-pressure gauge and brake components are not visible; the photo does not establish pressure build-up, absence of air leaks or parking-brake holding ability.

3. Tyres and wheel nuts

Not good / STOP

Alex reports a tyre sidewall bulge and requests STOP: vehicle must not operate. Close-up photo shows a pronounced outward sidewall bulge with surrounding cracking. Earlier exterior view covers only some left-side tyres and does not establish wheel-nut detail or complete tyre condition. Remaining wheels, opposite side and wheel nuts are unverified; Alex reports safe inspection access unavailable. Defect establishes STOP, not completion of all wheel checks.



Front-left exterior view of a yellow Mack dump truck at a quarry. Left front tyre and two outer rear tyres are visible, but the opposite side and inner rear tyres are not shown. Wheel-nut detail and complete tread/sidewall condition cannot be reliably assessed at this distance; this view does not establish the condition of all 10 wheels.



Close-up of a tyre showing a pronounced outward sidewall bulge with visible cracking around it. Only part of this wheel is visible; the image does not establish the condition of other tyres or wheel nuts.

4. Dump body

Unable to inspect / STOP

Alex reports safe access and qualified testing are unavailable and requests STOP pending safe reinspection. Photo shows a lowered dump body with aggregate visible above its sides and an exterior left wall view. Interior floor, complete welds, body chassis and rear view with tailgate open are not shown; absence of cracks, holes, distortion or load-spillage hazards cannot be established. No complete structural condition or functionality inferred.

Reason: Safe access and testing unavailable.



Front-left exterior view of a yellow Mack dump truck at a quarry, with dump body lowered and aggregate visible above its sides. The outer left body wall is visible, but the interior floor, complete welds, body chassis and rear view with tailgate open are not shown. This view cannot establish absence of cracks, holes or distortion throughout the body.

5. Hydraulics and fluids

Unable to inspect / STOP

Alex reports safe access and qualified functional testing are unavailable and requests STOP pending safe reinspection. Photo shows an exterior front-left view with body lowered and aggregate above its sides; hydraulic cylinder, pump, connections and mechanical supports are not clearly shown, and fluid levels are not visible. Hose condition, absence of leaks or drips, adequate fluid levels and smooth body raising/lowering remain unverified. No functionality inferred.

Reason: Safe access and testing unavailable.



Front-left exterior view of a yellow Mack dump truck at a quarry, with body lowered and aggregate visible above its sides. Hydraulic cylinder, pump, connections and mechanical supports are not clearly shown; fluid dipsticks and reservoir levels are not visible. This view cannot establish absence of leaks or drips, hose condition, fluid levels or smooth body raising/lowering.

6. Mechanical safety prop

Unable to inspect / STOP

Alex reports safe access and qualified functional testing are unavailable and requests STOP pending safe reinspection. Available photo shows a yellow dump truck with body lowered and aggregate above its sides. Both mechanical safety supports and locking pins are not clearly visible; their presence, straightness, pin condition and ability to fit and lock securely remain unverified. No functionality inferred; no raising or unsafe approach requested.

Reason: Safe access and testing unavailable.



Front-left exterior view of a yellow Mack dump truck at a quarry, with dump body lowered and aggregate visible above its sides. Both mechanical body safety supports and their locking pins are not clearly visible. This photo does not establish support presence, straightness, or ability to fit and lock securely with the body raised.

7. Tailgate and latch

Unable to inspect / STOP

Alex reports safe access and qualified functional testing are unavailable and requests STOP pending safe reinspection. Photo shows a front-left exterior view of a yellow dump truck with body lowered and aggregate above its sides. Rear tailgate face, latch engagement and hinge details are not clearly shown; frame and hinge condition, full closure and secure latch locking remain unverified. No functionality inferred; no unsafe approach requested.

Reason: Safe access and testing unavailable.



Front-left exterior view of a yellow Mack dump truck at a quarry, with dump body lowered and aggregate above its sides. The rear face of the tailgate, latch engagement and hinge details are not clearly shown. This view cannot establish tailgate frame and hinge condition, full closure or secure latch locking.

8. Lights and reflectors

Unable to inspect / STOP

Alex reports safe access and qualified functional testing are unavailable and requests STOP pending safe reinspection. Photo shows a front-left exterior view of a yellow dump truck with body lowered and aggregate above its sides. A front lamp assembly and cab roof marker lamps are visible without clearly demonstrated illumination; rear lights, both specified LED body lights and rear reflectors are not clearly shown. Operation of headlights, brake lights, indicators, reversing and body lights, and complete reflector presence and condition remain unverified. No functionality inferred.

Reason: Safe access and testing unavailable.



Front-left exterior view of a yellow Mack dump truck at a quarry, with body lowered and aggregate above its sides. A front lamp assembly and cab roof marker lamps are visible, without clearly demonstrated illumination. Rear lights, both specified LED body lights and rear reflectors are not clearly shown. The image does not establish light operation or complete reflector presence and condition.