Max. ambient temp.: 40°CDuty: continuous



HP		Nameplate RPM Over, 3.3" Bo	Rotation	Voltage	Full Loa Amps		Mounting	Stud/Base Mtg. Pattern	Stud Location*	Shaft Dia.	Shaft Length	Length Less Shaft	Cord Length	Item No.		1,100		-	ı
1/125	В	3000	CCWSE	115	0.49	Sleeve	Face	31/8" x 31/8"	2/BE	1/4"	3/4"	215/16"	6"	4M298	-	-3/2			
	С	3000	CWSE	115	0.60	Sleeve	Stud	27/8"	2/BE	1/4"	21/4"	2¾"	12"	3M537	86	5			
1/100 -	С	1550	CWSE	115	0.70	Sleeve	Stud	27/8"	2/SE	1/4"	21/4"	21/8"	12"	3M534			100	•	
7100	С	1550	CCWSE	115	0.70	Sleeve	Stud	21/8"	2/SE	1/4"	21/4"	23/4"	12"	3M535					
	С	1550	CWSE	115	0.70	Sleeve	Stud	21/8"	2/BE	1/4"	21/4"	2¾"	12"	3M536			1000		
	A	3000	CWSE	115	0.70	Sleeve	Stud	27/8"	2/SE	1/4"	13/8"	31/2"	12"	4M299				W.	
1/70 -	A	1550	CWSE	115	0.70	Sleeve	Stud	27/8"	2/BE	1/4"	21/4"	37/8"	16"	3M560			11 100		
	C	1550	CWSE	115	0.75	Sleeve	Stud	21/8"	2/BE	1/4"	21/4"	25/8"	21"	3M538			11 11		
	С	1550	CCWSE	115	0.75	Sleeve	Stud	27/8"	2/BE	1/4"	23/8"	2%"	21"	3M539	- 4	-	-	50	
_	C	3000	CWSE	115	0.80	Sleeve	Stud	21/8"	2/SE	1/4"	21/4"	21/2"	12"	3M729				Sea .	
1/50 -	C	1550	CWSE	115	0.80	Sleeve	Stud	27/8"	2/BE	1/4"	21/4"	31/16"	21"	3M542				100	
-	C	1550	CCWSE	115	0.85	Sleeve	Stud	2" x 2"	4/0SE	1/4"	21/4"	21/4"	10"	4M193 †				100	J.
	D	1550	CWSE	230	0.50	Sleeve	Stud	27/8"	2/SE	5/16"	21/4"	21/2"	12"	3M726		11111	The state of the s	S	0.
_	C	3000	CWSE	115	0.90	Sleeve	Stud	27/8"	2/BE	1/4"	23/8"	35/16"	12"	3M545					
-	E	3000	CCWLE	115	0.98	Sleeve	Stud	21/8"	2/BE	1/4"	21/4"	29/16"	12"	3M730		E I THE S			
	A	1550	CWSE	115	1.00	Sleeve	Stud	27/8"	2/BE	5/16"	2"	43/16"	15"	3M562		illi tem			
1/40 _	С	1550	CWSE	115	1.10	Sleeve	Stud	27/8"	2/BE	5/16"	25/16"	31/8"	12"	3M543	8	Till .			
-	С	1550	CCWSE	115	1.10	Sleeve	Stud	27/8"	2/BE	5/16"	25/16"	31/8"	12"	3M544		antes.	100	Z.	
_	D	1550	CWSE	115	1.10	Sleeve	Stud	27/8"	2/SE	5/16"	25/16"	21/2"	12"	3M722					
	E	1550	CWLE	115	1.15	Sleeve	Stud	21/8"	2/BE	5/16"	25/16"	5%"	12"	3M724	- 4	Million	11/	200	
_	D	3000	CWSE	230	0.60	Sleeve	Stud	21/8"	2/SE	5/16"	21/4"	31/8"	6"	3M725	- 4	1111411	7		
1/30 -	D	3000	CWSE	115	1.20	Sleeve	Stud	21/8"	2/SE	5/16"	23/8"	3"	12"	3M777		11/10/19	/		
-	C	1550	CWSE	115	1.20	Sleeve	Stud	2" x 2"	4/BE	5/16"	21/4"	31/2"	16"	3M546		1 1112	100		
	С	1550	CWSE	115	1.20	Sleeve	Stud	2" x 2"	4/SE	5/16"	23/8"	21/8"	21"	3M549		i ilie	Emily 1		K.
1/25 -	D	3000	CWSE	115	1.20	Sleeve	Stud	21/8"	2/SE	1/4"	21/4"	3"	12"	3M728		1111		1	
	F	1550	CWLE	115	1.80	Sleeve	Ring		2/BE		2%" & 2%		10"	4M195 †	-	-			
	D	1550	CWSE	115	2.10	Sleeve	Stud	2" x 2"	4/SE	5/16"	21/4"	2¾"	6"	3M778					
1/20	E	1550	CCWLE	115	2.10	Sleeve	Stud	2" x 2"	4/BE	5/16"	25/16"	53/16"	12"	3M083			10 14		
	E	1550	CWSE	115	2.00	Sleeve	Stud	2" x 2"	4/BE	5/16"	2"	31/2"	16"	3M547	1				
1/15 -	C	3000	CWSE	115	2.00	Sleeve	Stud	2" x 2"	4/SE	5/16"	21/4"	35/8"	16"	3M548					
	G	1550	CCWSE	115	2.50	Sleeve	Lug	61/8"	2/BE	5/16"	2"	3"	12"	4M301			2011	_	
Tota		closed Air-O						07/=	0.00	4.40	057.11	24/1			· 4	fl.	me A		
	H	1550	CWSE	115	0.60	Sleeve	Stud	27/8"	2/BE	1/4"	25/16"	31/4"	10"	3M552 †		HIEL	14,5		
1/100_	Н	1550	CCWSE	115	0.60	Sleeve	Stud	27/8"	2/BE	1/4"	21/4"	31/4"	10"	3M660 †	A)	29 10	18	SALES OF THE PARTY OF	
	<u> </u>	1550	CW/CCW	115	0.60	Sleeve	Stud	27/8"	2/BE	1/4"	23/8"	27/8"	12"	4M216		1 111		1	A .
1/70 -		1550	CWSE	115	0.70	Sleeve	Stud	27/8"	2/BE	1/4"	21/4"	27/8"	12"	3M554		1 111		1	, -
	<u> </u>	1550	CCWSE	115	0.70	Sleeve	Stud	27/8"	2/BE	1/4"	21/4"	213/16"	12"	3M661	1	The same	- A 20 1/2	100	STREET, STREET,
., -		1550	CWSE	115	1.00	Sleeve	Stud	21/8"	2/BE	5/16"	21/4"	3%"	12"	3M555			141	Marie 1	
1/40 _	<u> </u>	1550	CCWSE	115	1.00	Sleeve	Stud	27/8"	2/BE	5/16"	21/4"	3%"	12"	3M662	100		11 - 1	Nie	
	J_	1550	CWSE	115	1.10	Sleeve	Stud	27/8"	2/SE	5/16"	25/16"	23/4"	12"	3M556	-	30			_
		3000	CWSE	115	1.20	Sleeve	Stud	27/8"	2/BE	1/4"	29/16"	37/8"	12"	4M094					
1/30	<u> </u>	1550	CCWSE	115	1.20	Sleeve	Stud	21/8"	2/BE	5/16"	21/2"	31/2"	12"	4M199				•	
	K	1550	CWSE	115	1.20	Sleeve	Stud	2" x 2"	4/BE	5/16"	21/4"	3%"	15"	3M557	_		150		
iota	iiy En	closed Fan-				01	01.1	01 01	4.05	67.11	01/1	4178	401	F1/004				The same of the sa	
-	<u> </u>	1550	CWSE	115	2.0	Sleeve	Stud	2" x 2"	4/SE	5/16"	21/4"	41/4"	12"	5K001	A				
1/ -	<u> </u>	1550	CWSE	115	1.80	Ball	Stud	2" x 2"	4/SE	5/16"	21/4"	41/4"	12"	5K004		0		2	D/I
1/20	L	1550	CWSE	230	0.90	Sleeve	Stud	2" x 2"	4/SE	5/16"	21/4"	41/4"	12"	5K003	1000		1	1	M.
_	L	1550	CWSE	230	1.00	Ball	Stud	2" x 2"	4/SE	5/16"	21/4"	41/4"	12"	3M001	1		100		The same
	Ļ	1550	CCWSE	115	1.80	Ball	Stud	2" x 2"	4/SE	5/16"	21/4"	41/4"	12"	3M290	1		9		-
_	Ļ.	3000	CWSE	115	1.80	Sleeve	Stud	2" x 2"	4/SE	5/16"	21/4"	5"	12"	4M204		27	10.30		
1/15 -	L	1550	CWSE	115	2.30	Sleeve	Stud	2" x 2"	4/SE	5/16"	23/8"	41/2"	12"	3M363	6	9		Sec.	
	L	1550	CCWSE	115	2.30	Sleeve	Stud	27/8"	2/SE	5/16"	23/8"	41/2"	12"	3M291				100	
	M	1550	CWSE	115	2.30	Sleeve	Cradle Base	33/4" x 23/4"	2/BE	5/16"	2"	51/2"	12"	3M364	<	-			

M 1550 CWSE 115 2.30 Sleeve Gradie Base 394 x 294
*BE = Both Ends, SE = Shaft End, OSE = Opposite Shaft End. † 2-prong polarized plug.

41