Shaft Overall Item Length Length No.

95/16" 105/16"

6K4N2

6XH64 #

6XH78 ‡#

Shaft Dia.

Mounting

Cradle Base

Cradle Base



Split-Phase Open Dripproof Motors

Voltage

■ Rotation: CW/CCW

1725/1140 1725/1140

- Bearings: ball
- Max. ambient temp.: 40°C

Thermal Frame Protection

None

487

487

Open dripproof motors are for use in clean, dry, and nonhazardous applications including fans, blowers, pumps, printing equipment, and other business machines. NEMA 42 frame is supplied with a relay instead of a centrifugal switch; relay mounting clip is included. UL Recognized and CSA Certified.

Nom. Efficiency

43.4%

50.0% 50.0%

Full Load Service Ins. Amps Factor Class





		850	56	None	115	7.0	1.35	F	40.3%	Cradle Base	5/8"	17/8"	11 ¹³ /16"	6XH80 **
Ð		1725/1425	48Z	Auto	110/220	4.2/2.1	1.35	В	59.5%	Rigid Base	1/2"	17/8"	91/2"	6XJ46 *
	1/4	1725	48Z	None	115	5.3	1.35	В	52.0%	Cradle Base	1/2"	17/8"	913/16"	6XH65 ‡#
		1725	48Z	None	115	5.3	1.35	В	52.0%	Rigid Base	1/2"	21/4"	93/4"	6XJ35
		1725	48Z	None	230	2.5	1.35	В	53.7%	Cradle Base	1/2"	17/8"	913/16"	6XH61
		1725	48Z	Auto	115	5.3	1.35	В	52.0%	Cradle Base	1/2"	17/8"	913/16"	6K718 ‡
		1725	56Z	None	115	5.3	1.35	В	52.0%	Cradle Base	1/2"	17/8"	913/16"	5K280 #††
		1725	56Z	None	115	5.9	1.35	В	52.0%	Rigid Base	1/2"	17/8"	91/2"	5K279
		1140	56	None	115	5.5	1.35	В	53.6%	Cradle Base	5/8"	17/8"	1013/16"	6XJ57 **
		1140	56	None	208-230	2.7-2.9	1.35	В	58.7%	Cradle Base	5/8"	17/8"		24C177
		850	56	None	115	6.9	1.25	В	52.0%	Cradle Base	5/8"	17/8"	11 ¹³ /16"	6XH73 **
	1/3	3450	48Z	None	115	5.4	1.35	В	53.3%	Cradle Base	1/2"	17/8"	105/16"	5K586 ‡
		1725	48Z	None	115	7.0	1.35	В	54.3%	Cradle Base	1/2"	17/8"	913/16"	5K917
		1725	48Z	None	115	7.0	1.35	В	54.3%	Rigid Base	1/2"	21/4"	93/4"	6XH45
		1725	48Z	None	230	3.5	1.35	В	54.9%	Cradle Base	1/2"	17/8"	913/16"	6XH71 ‡
		1725	48Z	Auto	115	7.0	1.35	В	54.3%	Cradle Base	1/2"	17/8"	913/16"	5K601 ‡
		1725	48Z	Auto	230	3.5	1.35	В	54.9%	Cradle Base	1/2"	17/8"	913/16"	5K602 ‡
		1725	56Z	None	115	7.0	1.35	В	54.3%	Cradle Base	1/2"	17/8"	913/16"	5K534 ††
		1725	56Z	None	115	7.0	1.35	В	54.3%	Rigid Base	1/2"	17/8"	91/2"	5K281 ††
		1725	56Z	Auto	115	7.0	1.35	В	54.3%	Rigid Base	1/2"	17/8"	91/2"	5K412
		1140	56	None	115/230	6.7/3.4	1.35	В	60.3%	Cradle Base	5/8"	17/8"	1013/16"	6XH74 **
	1/2	3450	48Z	None	115	7.8	1.25	В	57.5%	Cradle Base	1/2"	17/8"	10%"	6K844 ‡
		1725	48Z	None	115	8.9	1.25	F	54.5%	Cradle Base	1/2"	17/8"	105/16"	6K764 ‡
		1725	48Z	None	115	8.9	1.25	F	58.8%	Rigid Base	1/2"	17/8"	915/16"	5K984
		1725	56	None	115	8.9	1.25	F	58.8%	Cradle Base	5/8"	17/8"	105/16"	5K283
		1725	56	None	230	4.6	1.25	В	59.7%	Cradle Base	5/8"	17/8"	1013/16"	5K288
		1725	56	Manual	115	8.9	1.25	F	58.8%	Rigid Base	5/8"	17/8"	915/16"	5K597
		1725	56Z	None	115	8.9	1.25	F	54.5%	Cradle Base	1/2"	17/8"	105/16"	4K913
		1725	56Z	None	115	8.9	1.25	F	58.8%	Rigid Base	5/8"	21/4"	105/16"	6XH82
	3/4	1725	56	None	115	11.3	1.25	В	63.6%	Cradle Base	5/8"	17/8"	115/16"	6XJ13
		1725	56Z	None	115	11.3	1.25	В	63.6%	Rigid Base	5/8"	21/4"	111/4"	6XJ24
	2 Spe					1.0.00.1			10.00/		4.4.0	.7	0407 =	
	<u>1/6, 1/18</u>	1725/1140	48Z	None	115	4.0/2.4	1.35	В	46.8%	Cradle Base	1/2"	17/8"	913/16"	6XH57 †#
	1/4, 1/8	1725/1140	48Z	None	115	4.6/4.3	1.35	F	52.5%	Cradle Base	1/2"	17/8"	105/16"	5K671 †‡
		1725/1140	56Z	None	115	4.9/3.3	1.35	В	53.0%	Cradle Base	1/2"	17/8"	105/16"	5K574 † ††
	1/3, 1/9	1725/1140	48Z	None	115	5.9/3.4	1.35	В	56.7%	Cradle Base	1/2"	17/8"	1013/16"	6XH75 †‡#
	.,	1725/1140	56	None	115	6.1/3.5	1.35	В	59.0%	Cradle Base	5/8"	17/8"	105/16"	6XH76 †**

No. 6XH57

Cradle-Base Mount

1/2, 1/4 1/25/1140 1.25 * 60/50 Hz. † 2-speed 115V switch No. 1DGZ9 available, see page 2929. ‡ Cradle base is notched to fit 48 and 56 frame mount. # Cradle with studs in a 3% "square pattern. ** Cradle with studs in a 43%" square pattern. †† Supplied with % "dia. shaft bushing.

230


None

3.8/2.8

Find Your Replacement Motor on Grainger.com®

Use our online MotorMatch® product selection quide to quickly and easily find the motor that meets your exact specifications. Drop-down menus for Horsepower, Nameplate RPM, Voltage, Enclosure, Motor Type, Mounting Preference, Bearing Type, and other options help narrow your search from thousands of choices.

Go to grainger.com/motors to locate your new or replacement motor today.



63.7%

Cradle Base