
PC 104 BUS
RAD SENSOR POWER SUPPLY
AX.25 PACKET TRANSMITTER
RAD SENSOR
EPS & CURRENT/POWER MONITOR
REAL TIME CLOCK
TEMP SENSOR
WATCHDOG
OBC - PIC18LF4620
PIC ICSP CONN.
PIC RESET
DEBUG SELECT
UART SELECT
FTDI CONN
HOST OBC COMM
TAMSAT - SIMPLESAT - B.ASUROGLU/O.DALAMAN 2015 v5.9