
FRC Sensor CAN · Rev A · TOP copper


Viewed from top; exported copper and drills, without solder mask



Nominal manufacturing geometry only. Compare to native KiCad, assembly and fabrication files.

FRC Sensor CAN · Rev A · BOTTOM copper

Viewed from bottom; exported copper and drills, without solder mask



Nominal manufacturing geometry only. Compare to native KiCad, assembly and fabrication files.