
# FRC Sensor CAN · Rev H SC12 · TOP copper


Viewed from top; exported copper and drills, without solder mask




Nominal manufacturing geometry only. Compare to native KiCad, assembly and fabrication files.

# FRC Sensor CAN · Rev H SC12 · BOTTOM copper

Viewed from bottom; exported copper and drills, without solder mask




Nominal manufacturing geometry only. Compare to native KiCad, assembly and fabrication files.