


Machine tag strips, segment 1/3 - 1.40 in tags every 3.20 in




cut columns apart; mount with each center tick at the labeled machine Y,
strip centered on the labeled X; tag rotation does not matter




scale check: ticks are 1 inch apart -- print at 100%


Machine tag strips, segment 2/3 - 1.40 in tags every 3.20 in



cut columns apart; mount with each center tick at the labeled machine Y,
strip centered on the labeled X; tag rotation does not matter



Machine tag strips, segment 3/3 - 1.40 in tags every 3.20 in




cut columns apart; mount with each center tick at the labeled machine Y,
strip centered on the labeled X; tag rotation does not matter



scale check: ticks are 1 inch apart -- print at 100%

Machine tag strips, segment 1/3 - 1.40 in tags every 3.20 in




cut columns apart; mount with each center tick at the labeled machine Y,
strip centered on the labeled X; tag rotation does not matter



scale check: ticks are 1 inch apart -- print at 100%

Machine tag strips, segment 2/3 - 1.40 in tags every 3.20 in





cut columns apart; mount with each center tick at the labeled machine Y,
strip centered on the labeled X; tag rotation does not matter



scale check: ticks are 1 inch apart -- print at 100%

Machine tag strips, segment 3/3 - 1.40 in tags every 3.20 in



Touch plate marker (ID 66), 0.753099 in square




glue to the touch plate, any rotation



scale check: ticks are 1 inch apart -- print at 100%


Lens calibration checkerboard (9x6 inner corners, 0.9 in squares)




mount on something rigid (cardboard/clipboard) and keep it flat



scale check: ticks are 1 inch apart -- print at 100%




rows 11-21 (this end toward machine rear / Y origin)




rows 0-10 (front end)


cut both segments at the dashed line and butt them together:
row 10 (top of right segment) sits directly below row 11



scale check: ticks are 1 inch apart -- print at 100%




rows 11-21 (this end toward machine rear / Y origin)



rows 0-10 (front end)

cut both segments at the dashed line and butt them together:
row 10 (top of right segment) sits directly below row 11



scale check: ticks are 1 inch apart -- print at 100%