#

Copyright © 2018 Broadcom. The term "Broadcom" refers to Broadcom Inc.

and/or its subsidiaries. This source file is the property of Broadcom

and may not be copied or distributed in any form except in strict

compliance with the relevant license agreement between Microsoft and

Broadcom.

#

CCEIP Memory Map			
Block	Start Address	End Address	
CCEIP Support Block	0x00000	0x0009F	
Inbound Stream FIFO	0x10000	0x100D7	
CRC Generator/Checker #0	0x20000	0x2007F	
Prefix Engine	0x30000	0x302FF	
Prefix Attach Engine	0x40000	0x4005F	
LZ77 Compression Engine	0x50000	0x5004B	
Huffman Compression Engine	0x60000	0x601EB	
CRC Generator #0	0x80000	0x8007F	
CRC Checker #0	0x90000	0x9007F	
XP10 Decompression Engine	0xB0000	0xB0123	
CRC Checker #1	0xD0000	0xD007F	
Completion Generator	0xE0000	0xE0017	
Outound Stream FIFO	0xF0000	0xF00af	
CCEIP Statistics Accumulator	0xF4000	0xF4057	
Scheduler Update	0xF8000	0xF8097	

CDDIP Memory Map			
Block	Start Address	End Address	
CDDIP Support Block	0x00000	0x0008B	
Inbound Stream FIFO	0x10000	0x100D7	
CRC Checker #0	0x20000	0x2007F	
Prefix Attach Engine	0x40000	0x4005F	
XP10 Decompression Engine	0x50000	0x50123	
CRC Generator #0	0x70000	0x7007F	
Completion Generator	0x80000	0x80017	
Outound Stream FIFO	0x90000	0x900af	
CDDIP Statistics Accumulator	0xA0000	0xA0057	
Scheduler Update	0xB0000	0xB0097	