



A COMMUNITY OF CHOICE

**Planning and Development Department**  
2101 O'Neil Avenue, Suite 202, Cheyenne WY 82001  
(Phone) 307-637-6282 (Fax) 307-637-6366

## MEMO

To: Honorable Mayor Patrick Collins and Members of the City Council  
From: Brandon T. Gilchrist, Planner I  
Subject: Conditions of the Blight Study-South Holliday Amendment  
Date: April 28, 2025

---

**Background:**

The item for consideration is a *Blight Study Amendment*. This is approved by Resolution.

The proposed Governing Body review schedule is as follows:

- Introduction and Referral April 28, 2025
- Public Services Committee May 5, 2025
- Final consideration May 12, 2025

**Urban Renewal Authority Board Recommendation:**

The Urban Renewal Authority Board heard this item at their April 3, 2025, meeting and approved this study unanimously.

The Blight study is attached.

**Attachments:**

1. Resolution
2. Urban Renewal Authority Staff Report

**RESOLUTION NO. \_\_\_\_\_**

**ENTITLED: “FINDING AND DECLARING CERTAIN AREAS WITHIN THE CITY OF CHEYENNE AS BLIGHT AND AUTHORIZING THE REDEVELOPMENT THEREOF IN ACCORDANCE WITH WYOMING STATUTE § 15-9-106.”**

WHEREAS, the City of Cheyenne has exercised its authority under Wyoming Urban Renewal Code, initiating the process of urban renewal within its jurisdictional boundaries;

WHEREAS, following public hearings held on June 14, 2021, and June 28, 2021, and in accordance with Wyoming Statute § 15-9-106, the Governing Body for the City of Cheyenne adopted Resolution No. 6156, designating certain parts of the City of Cheyenne as blighted and authorizing redevelopment in those areas;

WHEREAS, the City of Cheyenne has conducted a further study identifying additional areas, specifically along “South Holliday,” as blighted, based on the criteria set forth in Wyoming Statute § 15-9-103(iii), which includes properties that constitute an economic or social liability and are a menace to the public health, safety, morals or welfare in their present condition and use;

WHEREAS, the findings of this study, which are documented in Exhibit A, entitled “Conditions of Blight Amendment: South Holliday” and attached hereto and incorporated by reference, confirm that the statutory criteria for blight are met in these areas;

WHEREAS, in accordance with Wyoming Statute § 15-9-107, the Governing Body has determined that the areas described in Exhibit A are suitable for an urban renewal project; and

WHEREAS, the Governing Body hereby finds and declares the areas prescribed in Exhibit A to be blight and authorizes the necessary rehabilitation and redevelopment of these areas for the benefit of public safety, health, morals, and welfare for the residents of the City of Cheyenne.

NOW, THEREFORE, BE IT RESOLVED BY THE GOVERNING BODY OF THE CITY OF CHEYENNE, WYOMING, that the areas described in Exhibit A are hereby declared to be blight, and the rehabilitation and redevelopment of these areas are authorized as necessary for the public safety, health, morals, and welfare of the residents of the City of Cheyenne.

PRESENTED, READ AND ADOPTED THIS \_\_\_\_\_ DAY OF \_\_\_\_\_,  
2025.

---

Patrick Collins, Mayor

(SEAL)

ATTEST:

---

Kylie Soden, City Clerk



**Conditions of Blight  
Amendment:  
South Holliday  
City of Cheyenne  
(Exhibit A)**



Prepared March 2025  
Planning and Development  
Department

## **Table of Contents**

|                                    |           |
|------------------------------------|-----------|
| <b>Introduction</b>                | <b>2</b>  |
| <b>Blight Area Background</b>      | <b>2</b>  |
| <b>Conditions of Blight</b>        | <b>3</b>  |
| <b>Conclusions</b>                 | <b>13</b> |
| <b>Appendix A: Blight Surveys</b>  |           |
| <b>Appendix B: Blight Pictures</b> |           |

## Introduction:

On June 21, 2021, the Governing Body adopted Resolution No. 6156 declaring portions of the city of Cheyenne as blight and authorizing the redevelopment of those areas utilizing the urban renewal tools authorized under state statutes. The initial blight declaration included three areas of the community, the Reed Rail Corridor, the Hitching Post area on West Lincolnway, and properties referred to as the Hynds and the Hole northwest of Lincolnway and Capitol Avenue. Since adoption, the blight study has been amended to include these four other areas of the community:

- West 15th Street roughly between Bent and the Historic Depot (Resolution No. 6234 May 9, 2022),
- Jolly Rogers northwest of Whitney Road and U.S. 30 (Resolution No. 6334, July 10, 2023)

- Expanded Downtown generally west of Warren Avenue and east of Bent Avenue (Resolution No. 6334, July 10, 2023)
- Ridge and Holland which is an area of land west of Ridge Road and Holland Court (Resolution No. 6364 November 13, 2023).

## Blight Area Background

The South Holliday Blight Study area investigation was requested by the Urban Renewal Authority at their December XX, 2024 meeting and was an expansion of a request by a property owner in the area. The area outlined in yellow, referred to as "South Holliday," is situated in Cheyenne, Wyoming. E Lincolnway primarily bounds it to the north, Nationway to the east, and the railroad tracks along its



southern boundary. The outlined district, below, appears to be predominantly commercial and industrial, with numerous significant buildings, warehouses, and extensive surface parking lots. The blight study area also includes the property immediately northeast of Morrie Avenue and East Lincolnway which the City has declared surplus and is proposed for conveyance to a private developer.

## Conditions of Blight

City staff conducted a comprehensive survey using the guidelines outlined in Wyoming State Law to understand better which areas in Cheyenne may qualify for urban renewal. Specifically, the survey was based on nine conditions of blight listed in the Wyoming Urban Renewal Code (WY Stat. § 15-9-103(iii)). Although the law also defines slum conditions, these were not used separately in the survey since they closely overlap with the blight criteria.

Staff developed the survey to assess the following nine conditions—plus an “Other” category:

- Deteriorated or deteriorating buildings or structures
- Poor or unsafe street layout
- Faulty lot design (size, access, or usefulness)
- Unsanitary or unsafe environmental conditions
- Site deterioration or damaged infrastructure
- Complicated property ownership or tax issues
- Delinquent taxes that exceed the land’s value

- Legal title problems or irregularities
- Dangerous conditions that may endanger life or property (such as fire hazards)
- Other: This covers a broader definition from state law that includes factors impairing community growth, discouraging housing development, or creating a risk to public health, safety, or welfare.

For each condition observed, staff checked a box and wrote a brief description explaining what indicators were used to identify the issue. There was also space for notes on anything important that didn’t fit the predefined categories. Unlike some neighboring states, such as Colorado, Wyoming does not require a certain number of blight conditions for an area to qualify. That means the area can be considered blighted under state law if just one condition is found.

## Deteriorated or Deteriorating Structures

In the context of a blight study, deteriorated or deteriorating structures refer to buildings and infrastructure that show visible signs of physical decline, neglect, or damage, which can negatively impact an area's overall quality, safety, and aesthetics. This criterion is critical because the condition of structures significantly influences property values, livability, and the community's ability to attract new investments or residents.

### Characteristics of Deteriorated or Deteriorating Structures:

- **Physical Damage:** Includes issues like cracks in walls or foundations, broken windows, collapsing roofs, or unstable structural elements.
- **Neglect:** Prolonged lack of maintenance leading to peeling paint, rusted fixtures, overgrown landscaping, or damaged exteriors.
- **Obsolete Design:** Due to outdated building materials or layouts, structures no longer meet modern safety, efficiency, or use standards.
- **Unsafe Conditions:** Problems such as exposed wiring, mold, or significant water damage that pose health and safety risks.
- **Poor Maintenance:** Cracked pavement, potholes, faded markings, or obstructed signage that compromise the usability and safety of the streets.

### Findings

Currently, the study area exhibits limited visible evidence of deteriorated or deteriorating structures. Most of the existing commercial and industrial buildings within the boundary appear structurally sound, and significant physical damage or noticeable signs of neglect are not readily apparent from aerial observations. However, the city recognizes several parcels, mainly vacant lots, unused parking areas, and underutilized buildings, present a lack of activity and investment. Over time, this ongoing inactivity, if not proactively addressed, could contribute significantly to deterioration criteria, including structural degradation, increasing neglect, and potential physical decline.

Specifically, the presence of multiple vacant or minimally utilized lots, especially those adjacent to the railroad tracks, suggests that if left unmanaged, these areas could experience gradual deterioration through reduced property maintenance, deferred upkeep, and encroachment by overgrown landscaping or debris accumulation.

Although immediate conditions in South Holliday do not yet strongly reflect deterioration, the City of Cheyenne recognizes that ongoing inactivity and underutilization in several vacant lots and buildings could, over time, increase vulnerability to structural degradation and broader blight characteristics.



*A dilapidated structure within the expansion area.*

### Predominance of Defective or Inadequate Street Layout

In the context of a blight study, the predominance of defective or inadequate street layout refers to the widespread presence of street systems that are poorly designed, improperly maintained, or insufficient to meet the needs of the community. These issues can hinder accessibility, safety, and overall functionality, negatively impacting residents and businesses.

## Characteristics of Defective or Inadequate Street Layout

- **Lack of Connectivity:** Streets that do not adequately link neighborhoods, commercial areas, or public spaces, resulting in dead ends, cul-de-sacs, or isolated areas.
- **Improper Design:** Streets that are too narrow, too wide, or poorly aligned, creating inefficiencies **and safety hazards**.

## Findings

South Holliday exemplifies a range of urban challenges that inhibit its potential as a dynamic and functional urban environment. Issues in connectivity, design, infrastructure efficiency, and maintenance collectively constrain the area's growth and vitality.

## Lack of Connectivity

Effective connectivity is essential for integrating urban spaces with their surroundings, promoting accessibility, and fostering community cohesion. Unfortunately, South Holliday suffers from a notable lack of connectivity, which isolates it from key urban arteries and neighboring areas.

- **Limited Accessibility:** The area's dearth of direct and coherent routes limits its integration with adjacent residential, commercial, and industrial zones, stifling economic and social interactivity. Access limitations include arterial streets within the area and the Union Pacific railroad to the south.
- **Fragmented Pathways:** Incomplete sidewalks and the absence of multimodal transport options restrict pedestrian and cyclist movement,

diminishing the area's inclusivity. This includes sidewalks and greenway paths.

## Improper Design

The spatial design and organizational structure of South Holliday reflect a misalignment between current usage patterns and the needs of a diverse urban populace.

- **Lack of Cohesion:** The absence of a unified design strategy results in fragmented land use and undefined spaces, impeding the area's potential to thrive as a harmonious urban district.
- **Neglect of Human Scale:** A deficiency in walkable environments, active street-level zones, and public spaces undermines efforts to establish an engaging and vibrant urban atmosphere.
- **Underutilized Parcels:** Numerous vacant or inefficiently utilized parcels reflect a missed opportunity for the area to perform as a productive urban asset.



*Right-of-way improvements and private property improvements have fallen into disrepair.*

## Insufficient Infrastructure

Robust infrastructure is the backbone of urban efficacy, yet South Holliday exhibits significant deficiencies.

- **Poor Transportation Infrastructure:** Narrow roads, insufficient traffic management, and inadequate parking facilities hamper fluid movement in and around the district.
- **Missing bicycle and pedestrian links.**
- **Utility Gaps:** Deficiencies in essential utilities, such as outdated drainage systems, insufficient street lighting, and unreliable services, hinder operational efficiency for both residents and businesses.

### **Poor Maintenance**

Without proper upkeep, urban areas can quickly fall into a state of neglect, as evidenced by South Holliday

- **Degraded Public Spaces:** Existing pathways and communal areas show signs of disrepair, discouraging use and contributing to a negative perception of the area.
- **Unkempt Vacant Land:** Overgrown and littered vacant parcels detract from the district's aesthetic and pose safety concerns.
- **Infrastructure Decay:** Crumbling sidewalks and other neglected infrastructure elements reflect inadequate maintenance.

### **Faulty Lot Layout in Relation to Size, Accessibility or Usefulness**

In a blight study, faulty lot layout in relation to size, accessibility, or usefulness refers to land parcels that are poorly configured, improperly sized, or difficult to access, making them unsuitable for efficient or practical use. These issues often result from outdated planning



*Above and below: Examples of poor public infrastructure and private property improvements.*



practices, neglect, or improper land subdivisions, and they can hinder development and reduce the area's functional and economic potential.

### **Characteristics of Faulty Lot Layout**

- **Irregular Lot Shapes:** Lots with awkward or non-standard shapes that complicate development or limit usability.
- **Inadequate Lot Size:** Parcels that are too small or too large for their intended purpose, resulting in inefficiency or underutilization.

- **Poor Accessibility:** Lots without proper road frontage, easements, or connections to essential infrastructure, such as utilities or transit.
- **Incompatibility with Zoning Requirements:** Parcels that do not meet current zoning standards, making development or redevelopment challenging.
- **Obsolete Subdivisions:** Legacy lot layouts no longer align with contemporary urban design or planning principles.



*Above: Map showing diverse parcel ownership. Below: Map showing faulty platted lot layout in the study area.*



## Findings

In assessing the South Holliday area, it is important to consider how lot configurations and roadway alignments impact accessibility, development potential, and site utilization. The district presents various parcel shapes, sizes, and orientations, many of which pose distinct access limitations. Specifically, the presence of irregular lot shapes—some narrow, elongated, or triangular—creates significant constraints for efficient site planning, building layout, and vehicular access. Such parcels often complicate the placement of ingress and egress points and limit practical design options for redevelopment, potentially influencing the feasibility of commercial or industrial operations

that require predictable and efficient vehicle circulation and access.

Additionally, the area is significantly influenced by engineering-driven access spacing standards that affect where driveway entrances or connections to primary roadways, such as E Lincolnway and Nationway, can feasibly occur. Engineering standards regarding minimum spacing between driveways and intersections,

aimed at ensuring traffic safety and flow, result in limited entry and exit points for several parcels. Consequently, some properties may remain underutilized or undeveloped due to these restrictions, further contributing to an environment vulnerable to blight.

General characteristics of the local roadway alignments also present access challenges. The major roadways defining the area boundary, notably Nationway and E Lincolnway, include extended curves and significant curvature, reducing visibility and limiting available sight distances. These extended curves and the alignment of major intersections introduce additional engineering complexities for safe vehicular ingress and egress. Sites near these curves or intersections, particularly around the Lincolnway and Nationway intersection and eastern roundabout area and the junction at Morrie Avenue, face reduced visibility and increased difficulty meeting safe access standards.

The irregular shapes of parcels, combined with stringent engineering access spacing standards and challenging roadway alignments—characterized by significant curves, roundabouts, and intersections—collectively contribute to limited accessibility and reduced developability in the South Holliday area. These conditions may influence land use efficiency and intensify long-term issues related to blight if proactive planning and intervention measures are not considered.

## **Deterioration of Site or Other Improvements**

In the context of a blight study, deterioration of site or other improvements refers to the

physical decline or neglect of features beyond buildings, such as parking lots, landscaping, sidewalks, signage, and other infrastructure. These elements contribute to a site's functionality and appearance, and their deterioration signals a lack of maintenance that negatively impacts the community's aesthetics, safety, and usability.

### **Characteristics of Deterioration of Site or Other Improvements**

- Public Street improvements, too (from above)
- Damaged Paved Surfaces: Cracks, potholes, or erosion in parking lots, driveways, and sidewalks.
- Neglected Landscaping: Overgrown vegetation, dead plants, or lack of proper maintenance of green spaces.
- Poorly Maintained Amenities: Broken benches, playground equipment, or recreational facilities.
- Degraded Fencing and Boundaries: Rusted, damaged, or missing fencing and barriers.
- Faded or Damaged Signage: Worn-out business signs, street signs, or directional markers.
- Drainage Issues: Blocked or broken stormwater systems causing pooling or flooding.

### **Findings**

South Holliday in Cheyenne, Wyoming, faces numerous maintenance challenges that hinder its functionality, safety, and aesthetic appeal. These issues range from structural damage to neglect of public and private amenities, affecting the area's usability and overall impression.

### Damaged Paved Surfaces

The paved surfaces within the expansion area, including parking lots, driveways, and sidewalks, exhibit significant damage. Cracks, potholes, and erosion are widespread, creating hazards for pedestrians and vehicles alike. These damaged surfaces diminish the area's functionality and contribute to a negative perception of the site. Immediate repairs and resurfacing are necessary to restore these surfaces and improve safety and usability.

### Neglected Landscaping

The landscaping within South Holliday appears to suffer from a lack of consistent maintenance. Overgrown vegetation, dead plants, and unkempt green spaces dominate the area. These neglected conditions detract from the site's aesthetic value and discourage community engagement. Proper upkeep, including routine trimming, replanting, and irrigation, is crucial to revitalizing the landscape and enhancing the area's visual appeal.

### Degraded Fencing and Boundaries

Fencing and barriers within South Holliday show signs of rust and damage and, in some cases, are entirely missing. This creates an unsafe and unstructured environment while reducing, reducing the area's overall security. Replacing or repairing these boundaries with durable materials and maintaining them regularly would improve safety and establish clear perimeters.

### Faded or Damaged Signage

Many of the area's business signs, street signs, and directional markers are faded, worn out, or damaged. This creates confusion for visitors and detracts from the site's professional

appearance. Replacing or updating signage with durable and weather-resistant materials would enhance navigation and the overall impression of South Holliday. "The Yard."

### Drainage Issues

Stormwater management systems in South Holliday appear blocked or broken, resulting in pooling or flooding during rainfall. These drainage issues can lead to property damage, safety hazards, and further deterioration of paved surfaces. Addressing these problems through routine cleaning, repairs, and modern drainage solutions is essential for the site's resilience and functionality.

## **The Existence of Conditions which Endanger Life or Property by Fire and other ...causes**

In a blight study, the existence of conditions which endanger life or property by fire and other causes refers to physical, environmental, or situational hazards that pose significant risks to safety and property. These conditions often arise from neglect, poor maintenance, or improper design and can contribute to the decline of a community by increasing the risk of disasters and undermining residents' sense of security.

### **Characteristics of Conditions Endangering Life or Property**

- Fire Hazards:
- Overgrown vegetation or debris that increases fire fuel loads.
- Faulty or outdated electrical systems are prone to sparking fires.

- Lack of firebreaks or adequate fire suppression systems, such as hydrants or sprinklers.
- Structural Hazards:
  - Collapsing or unstable buildings that may endanger nearby structures or people.
  - Inadequate exits or escape routes in case of emergencies.
- Environmental Risks:
  - Poorly maintained or absent drainage systems lead to flooding.
  - Hazardous material storage or spills, such as chemicals or flammable substances.
- Infrastructure Risks:
  - Lack of street lighting, creating conditions for accidents or crime.
  - Broken or missing utility infrastructure, such as gas leaks or exposed wiring.
- Floodplain:
  - A portion of the South Holliday area is within the City-defined Holliday Basin 100-year floodplain which. In addition to Federal Emergency Management Agency (FEMA) defined flood hazard areas, the City has established local flood hazard areas based on local flooding conditions to promote the public health, safety and general welfare and to minimize public and private losses due to flood conditions.

## Findings

The study area presents additional concerns, particularly environmental vulnerabilities linked to its proximity to the railroad. The potential for environmental concerns is increased due to

possible contamination from railroad-related activities and historical industrial operations. Although no direct evidence of current or ongoing contamination was found, parcels near the railroad are susceptible to contamination risks from hazardous substances commonly associated with rail operations.

Further environmental risks include portions of the study area within the City-established local flood hazard zones, notably the South Holliday area, where segments fall within the Holliday 100-year floodplain. In addition to the Federal Emergency Management Agency (FEMA)-defined flood hazard areas, the City of Cheyenne has identified local flood hazard zones based on historical and site-specific flooding conditions. This proactive approach is intended to safeguard public health, safety, and general welfare and minimize both public and private losses due to flooding. Poorly maintained or absent drainage systems in the area exacerbate these environmental risks, significantly increasing vulnerability to flooding events, particularly during intense rainfall.

Furthermore, the industrial nature of the area heightens the likelihood of hazardous material storage or accidental spills, posing further threats to environmental quality.

Infrastructure concerns, including inadequate street lighting, compound these environmental risks, increasing the potential for accidents and crime. Additionally, the irregular parcel shapes, stringent engineering access spacing standards, and challenging roadway alignments—including major intersections and significant curves—limit site visibility and accessibility, further endangering life or property.

The combined factors of proximity to railroad infrastructure, local flooding hazards, irregular parcel shapes, engineering constraints, and roadway alignment issues collectively underscore the area's vulnerability. These considerations highlight the necessity for strategic urban planning and proactive interventions to mitigate existing risks and prevent future blight.



*General locations of mapped City and FEMA flood hazard areas.*

## Conclusions

The South Holliday study area in Cheyenne demonstrates several criteria indicative of potential blight, despite exhibiting limited visible structural deterioration. Predominantly commercial and industrial, the district includes numerous large buildings, warehouses, parking lots, and multiple vacant or minimally utilized parcels, notably adjacent to railroad tracks, suggesting potential sites for redevelopment.

Although immediate structural deterioration is minimal, the persistent inactivity and underutilization of several lots and structures pose long-term risks. Specifically, parcels near the railroad tracks have heightened vulnerability due to potential environmental contamination associated with railroad operations and historical industrial uses. The proximity to railroad infrastructure raises concerns about hazardous materials spills and contamination risks.

Most of the South Holliday area is within the City-defined Holliday Basin 100-year floodplain. Beyond FEMA-designated flood hazard areas, the City of Cheyenne has proactively established local flood hazard zones based on site-specific flooding conditions, aiming to protect public health, safety, and welfare and reduce flood-related damages. Poorly maintained or

insufficient drainage systems amplify flooding risks, further exacerbating environmental vulnerabilities. Infrastructure issues also prominently affect this area. Inadequate street lighting potentially increases crime and accident risks, while irregular lot shapes and limited street connectivity pose accessibility challenges. Parcel configurations and existing roadway alignments, including significant curves and intersections, reduce sight distances, restrict safe ingress and egress, and complicate compliance with engineering spacing standards.


The proximity to railroad infrastructure presents additional environmental risks due to potential contaminants associated with rail operations, hazardous material storage, and industrial activities, emphasizing the necessity for careful ecological assessment and proactive intervention.

These factors—irregular lot configurations, access limitations due to engineering spacing standards, inadequate infrastructure, proximity to the railroad, and local floodplain conditions—underscore the area's susceptibility to blight. Strategic, proactive urban planning interventions will be essential to mitigate these vulnerabilities and enhance South Holliday's long-term viability and resilience.

# **Conditions of Blight**

## **Appendix A**

### **Blight Surveys**





## City of Cheyenne — Blight Survey

Location Description:

Completed By: Brandon T. Gilchrist

Date Surveyed: 01/2025

| Criteria:                                                          | Criteria exists on site:            | Description of Conditions:                                                                                                                                                                                                                                                                                                                                                                                                                               |
|--------------------------------------------------------------------|-------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Deteriorated or Deteriorating Structures                           | <input checked="" type="checkbox"/> | <ul style="list-style-type: none"><li>○ The visible wear and tear on roadways, sidewalks, and other infrastructure is a primary indicator of neglect and lack of investment. This reflects a broader trend of deferred maintenance that has exacerbated the district's decline.</li><li>○ The lack of pedestrian-friendly infrastructure contributes to safety concerns and limits walkability, a key factor in fostering vibrant urban areas.</li></ul> |
| Predominance of Defective or Inadequate Street Layout              | <input checked="" type="checkbox"/> | <ul style="list-style-type: none"><li>○ Visible areas within the area aging and deteriorating infrastructure, including worn roadways and poorly defined lot boundaries.</li><li>○ Sidewalks are minimal or nonexistent in key areas, reducing accessibility and safety for pedestrians.</li></ul>                                                                                                                                                       |
| Faulty Lot Layout in Relation to Size, Accessibility or Usefulness | <input checked="" type="checkbox"/> | <ul style="list-style-type: none"><li>○ Irregular lot shapes and fragmented land use reflect a lack of cohesive urban planning. This disjointed layout limits efficient land utilization and creates barriers to integrated development.</li><li>○ The mix of residential, commercial, and industrial properties lacks synergy, preventing the district from</li></ul>                                                                                   |



## City of Cheyenne — Blight Survey

|                                                          |                                     |                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|----------------------------------------------------------|-------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                                                          |                                     | functioning as a cohesive community.                                                                                                                                                                                                                                                                                                                                                                                                               |
| Unsanitary or Unsafe Conditions                          | <input type="checkbox"/>            | <ul style="list-style-type: none"><li>Major roads such as East Lincolnway and Logan Avenue prioritize vehicle traffic, with little consideration for pedestrians or cyclists.</li><li>The absence of well-marked crosswalks, bike lanes, and transit stops hinders safe and equitable access to the district.</li><li>The district's proximity to the rail yards creates challenges for traffic flow and limits access to certain areas.</li></ul> |
| Deterioration of Site or Other Improvements              | <input checked="" type="checkbox"/> | <ul style="list-style-type: none"><li>The combination of neglected properties, outdated infrastructure, and poor maintenance creates an overall perception of urban decline.</li><li>The district's visible blight impacts neighboring areas, lowering property values and deterring investment.</li></ul>                                                                                                                                         |
| Criteria:                                                | Criteria exists on site:            | Description of Conditions:                                                                                                                                                                                                                                                                                                                                                                                                                         |
| Diversity of Ownership, Tax or Other Special Assessments | <input type="checkbox"/>            |                                                                                                                                                                                                                                                                                                                                                                                                                                                    |



## City of Cheyenne — Blight Survey

|                                                                                              |                          |  |
|----------------------------------------------------------------------------------------------|--------------------------|--|
| Delinquency<br>Exceeding the Fair<br>Value of the Land                                       | <input type="checkbox"/> |  |
| Defective or<br>Unusual Conditions<br>of Title                                               | <input type="checkbox"/> |  |
| Existence of<br>Conditions which<br>Endanger Life or<br>Property by Fire and<br>Other Causes | <input type="checkbox"/> |  |
| Other                                                                                        | <input type="checkbox"/> |  |

Notes:

# **Conditions of Blight**

## **Appendix B**

### **Blight Photos**

