


Add 6 pin connector

Foot print is; Connector\_JST:JST\_XA\_B06B-XASK-1\_1x06\_P2.50mm\_Vertical

Connector ozdisan code: L-KLS1-2.50-06-S

And follow the same order; 1-motor RIN(IN1), 2-motor FIN(IN2), 3-led driver control, 4-relay control, 5-gnd, 6-5v

Take 5v for battery charge circuit from 12v to 5v buck convertor output (no need to add battery charger 5v connector)



Add header to ecg output

foot print is: Connector\_PinHeader\_2.54mm:PinHeader\_1x02\_P2.54mm\_Vertical

ozdisan code: L-KLS1-207-1-02-S

Select the connector for ecg input and connect the same circuit related with HW5 answer

Ozdisan code is: L-KLS1-TPJ3.5-002C