

u_1, u_2 — motor currents (inputs)
 θ_{h1}, θ_{h2} — joint angles (encoders)
 θ_{t1}, θ_{t2} — link deflections (strain gauges)

