



Issue

CE and RE were switched so that CON3 was CE1 to CE16 and CON2 was RE1 to RE16.

Original Schematic:




Original PCB:



EmStat Pico MUX16 pinout correction

Corrected Schematic:



Corrected PCB:

