```
PROGRAM PLC PRG
 1
        L1 AT %QX0.0: BOOL;
            L2 AT %QX0.1: BOOL;
            L3 AT %QX0.2: BOOL;
            L4 AT %QX0.3: BOOL;
 7
            Q1 : INT := 0;
 8
            Q2 : INT := 0;
            Q3: INT := 0;
Q4: INT := 0;
 9
10
            W1 : INT ;
11
           W2: INT;
12
13
           W3 : INT ;
14
           W4: INT;
        wynik1: INT;
robot1 AT %QX0.4: BOOL := FALSE;
robot2 AT %QX0.5: BOOL := FALSE;
robot3 AT %QX0.6: BOOL := FALSE;
robot4 AT %QX0.7: BOOL := FALSE;
15
16
17
18
19
           B4: INT;
20
21
            B3 : INT ;
22
            B2 : INT ;
23
            B1 : INT ;
24
       END_VAR
25
```





