

Common utility rail
becomes invalid



Backplane qualified rail-
health output pulls OK low



Fleet enters ERROR; boards
remain powered for diagnosis

Shared interlock remains powered

One board loses
V_INTERLOCK_LOCAL



Hardware reports F6; local
relay permission is removed



Fleet enters ERROR; unaffected
boards remain available

Affected-board telemetry may be limited

Central eFuse discon-
nects protected +12V



Complete downstream
power tree turns off



All powered outputs
and normally-open
relays de-energize

Continued OK and telemetry are not required