


The ADC time base may be related to sequencer timing; this example imposes neither independence nor a fixed frequency ratio.



Management and safety do not depend on distributed CLOCK.
The watchdog timeout time base must survive loss of its supervised clocks.



Optional board-local converter clocks may derive from CLOCK;
an EN=0 alignment SYNC affects only compatible local dividers.