## **Table of Contents**

Page	itle Page Title		Title	Page Title
01		31	Sensor-uC	61 +1VSB
02	CHANGE HISTORY	32	On Board-Sensors	62 +1.8VSB & Load SW
03	BLOCK DIAGRAM	33	Debug Conn	63 CHARGER
04	CLOCK DISTRIBUTION	34	Empty	64 +5V Load SW
05	SIGNAL & RESET MAP	35	SM BUS	65 +3P3V Load SW
06	POWER FLOW	36	EC-ITE 8528VG-1	66 VCPU Controller
07	POWER DISTRIBUTION	37	EC-ITE 8528VG-2/SPI ROM	67 VCORE VCCSA
08	POWER SEQUENCE	38	ТРМ	68 VCVGT
09	I2C MAP	39	Temp Sensor/System Fan	69 EMPTY (was GTX Reg)
10	CPU(1)_MISC,JTAG,DDI.EDP	40	REALTEK ALC298 CODEC	70 SL1 PWR/ BATT CONN.
11	CPU(2)_LPDDR3	41	Audio Jack/Vol Button/Spkr	71 SL1 SIGNALS
12	CPU(3)_SKL POWER1	42	Microphones	72 +3P3V_HPD/LCD backlight/TB
13	CPU(4)_SKL_POWER2	43	M.2 SSD CONNECTOR	73 BLADE PWR
14	CPU(5)_GND	44	Empty	74 BLADE
15	CPU(6)_CFG_RESERVED	45	USB3.0	75 Power Protect
16	LPDDR3(1)_MEMORY DOWN	46	DP Dongle Control	76 Test Points
17	LPDDR3(2)_MEMORY DOWN	47	mDP	
18	XDP	48	SDXC	
19	LPDDR3(3)_CA/DQ Voltage	49	Camera IR	
20	PCH(1)_SD,HDA,RTC, CLK	50	Wi-Fi_BT	
21	PCH(2)_CLK,SMB,LPC, SPI	51	Components for ME/EMI	
22	PCH(3)_SYS PWR CONTR	52	Camera Power	
23	PCH(4)_CCI, HWID	53	Camera Rear	
24	PCH(5)_PCIE,USB	54	Camera Front	
25	PCH(6)_CPU,GPIO,MISC	55	3P3VA & BKL PWR	
26	PCH(7)_POWER	56	+VCCIO & OP85VSB	
27	PCH(8)_empty	57	eDP connector	
28	Power Monitor	58	+VCCEDRAM & +VCCEOPIO	
29	Empty	59	+5VSB & +3P3VSB	
30	Touch Con & Key	60	+1P2V_DUAL&+VTT	

CAD Note:
Default component footprint is SMD 0201, X5R, 1% resistors.

Property: BUILD-OPT
DNP = Do Not Place
Vinafix.com

S or DB = Replace after Debug

<core< th=""><th>Design&gt;</th><th></th></core<>	Design>	
	Title:	<b>Table of Contents</b>
	Engineer:	Surface
Size	Project Name	Rev
A3	U EV 1.9	1.90.2
Date:	Monday, May 11, 2015	Sheet 1 of 76

## **Schematics Change History**

Rev.	Date	Comments
0p9	28 Oct 2014	1. Starting with G_EV1_1021-1630.DSN 2. Added SL schematic from page 72\T\MB\DV_RELEASED\Schematic\CASTLE2_DV_2014_1021_1100.DSN 3. Added External USB3 schematic from\T\MB\DV_RELEASED\Schematic\CASTLE2_DV_2014_1021_1100.DSN 4. Added external DP\T\MB\DV_RELEASED\Schematic\CASTLE2_DV_2014_1021_1100.DSN 5. Added IR_CAMERA from Front Cameraput in page 49 6. Removed page 73 PCIE GPU 7. Added Blade from T 8. Removed P72 T2B Pwr Transistors
0p10	3 Nov 2014	1. Changing to NVDC 2. Replaced GTX with GT, kept bypass caps 3. Replaced Charger with BQ24770
0p11	3 Nov 2014	1. Replace SKL-U with SKL-Y
0p12	11 Nov 2014	1. Model DDR connection from Intel SDS
0p13	18 Nov 2014	<ol> <li>Added FUB information to all components</li> <li>Changed Decretes sizing caps</li> </ol>
0p14	20 Nov 2014	1. Added +5VA_SHA 2. Added T Cost Down/XCN's 3. Added SL +5V load Switch & Caps 4. Added Blade +5V load Switch & Caps
0p15	26 Nov 2014	1. Removed Boost 2. Re-adjusted usb ports on CPU 3. Removed Audio DSP
0p16	03 Dec 2014	1. changed +1VSB regulator 2. changed IR Camera/added diode 3. added power numbers from 0.91 PDG, Oct14 4. changed BLADE connector 5. cpu decoupling caps changed 6. changed +5V/+3V inductors (place holder)
0p17	05 Dec 2014	1. swapped M_A_CAA with MA_CAB on U1601/U1602 2. added two SAR chips, P32 3. remove tp's from csi lines on (p23) 4. change from 10 ceramic to 3 tantalum-poly on usb3 typeA (p45) 5. remove the RSENSE from output of +VCCIO(p56)/+Op85VSB(p56)/+VCCEDRAM (p58)/+VCCEDRAM (p58
0p18	09 Dec 2014	1. Reduced sizes of parts for Cameras (Resistors/Caps/Regulators)
0p19	12 Dec 2014	1. All 47uF caps become 0805/1mmZ 2. All 10uF caps become 04024V/6.3V
0p20	15 Dec 2014	<ol> <li>changed SAM flash to reduce size to 2x3 from 5x4</li> <li>Shui Changes</li> <li>more Shui Changes</li> </ol>
0p21	16 Dec 2014	1. changed SAM flash to reduce size to 2x3 from 5x5 2. changes from EV_schematic_issue_check_1216_JDM1.xlsx 3. changed name of +6_12 to +V_ALWAYS_ON 4. Removed 2 Mikes & Front Mike & added FPC conn 5. Added 2nd BLADE connector
0p22	17 Dec 2014	1. Replaced SD connector with AY531465T 2. changes from EV_schematic_issue_check_viola_1217_JDM1.xlsx
0p23 - current		1. See apexUfixes_revXpXX.xlsx


CAD Note:
Default component footprint is SMD 0201, X5R, 1% resistors


S = Short after design fixed


Property: BUILD-OPT


Vipaffy Com = Not Installed Part.


			C	CHANGE HISTORY-1							
				Engineer:		Surf	ace				
Size	Project Name								Rev		
А3		<b>U</b> -	-	<b>EV 1.90</b>					1.90.2		
Date:	Monday, May	11, 201	5		Sheet	2	of	76			




























































				PCH														
				Processor				EC Board					DR	AM	RAM			
Rev	4	EC Proce	essor ID	ID		TPM		Rev		PCH Board ID[3:0]			Manufacturer		Speed	<b>RAM Size &amp; Calibration</b>		
Sigr	al	EC_ID1	ED_ID0	PCB_ID5	PCB_ID4			R3619	PCB_ID3	PCB_ID2	PCB_ID1	PCB_ID0	MEM_ID1	MEM_ID0	MEM_ID4	MEM_ID3	MEM_ID2	ZQ1
																		R1602
						R3813												R1604
	1	. = R3642	1 = R3640	1 = R2323	1 = R2303	R3815			1 = R2307	1 = R2305	1 = R2306	1 = R2304	1 = R2315	1 = R2318	1 = R2321	1 = R2319	1 = R2320	R1702
	0	) = R3643	0 = R3641	0 = R2324	0 = R2301	R3816	R3814		0 = R2310	0 = R2309	0 = R2308	0 = R2302	0 = R2316	0 = R2317	0 = R2314	0 = R2313	0 = R2312	R1704
															1600			4GB =
		U22=0	U22=0		Infineon	Infineon	Infineon						l basisa — O	I banisa — O	LPDDR3 =	4CD - 0	4 CD = 0	DNP
	ι	U23E = 1	U23E=0	U=0	=0	= DNP	= POP						•	Hynix = 0	l ()		4 GB = 0	8GB =
		Y=0	<b>Y</b> = <b>1</b>	Y = 1	Nation Z	NationZ =	NationZ						_	Samsung	1866		8GB=1	POP
		S=1	S = 1		=1	POP	=DNP						=0	=1	LPDDR3 =	10GB = 1	16 GB = 0	16GB =
															1			POP
EV 0.9	)							80.6Ω	0	0	0	0						
EV 1.0	)							169 Ω	0	0	0	1						
EV 1.5	;							698 Ω	0	0	1	0						
EV 1.9	)			_				909 Ω	0	0	1	1						

TBL2301













Title: PCH(8)\_empty Engineer: Surface U -- EV 1.90 1.90.2 Vinafix.com































## Trusted Platform Module +3P3V +3P3V TPM DB,TPM R3817 0.010 res\_0603\_30mil +3P3V\_TPM -O PMTP3801 SP-tp-c0p381 +3P3V\_TPM PMTP3802 -O PM1 P3002 SP-tp-c0p381 TBL2301,TPM R3815 +3P3V\_TPM 100K RES\_0201\_12mil X813010-001 +3P3V\_TPM TBL2301,TPM U3801 SLB9665TT2.0FW5.40 tssop28\_9p7x4p4x1p1\_p65mm TPM C3801 -- 0.1u 6.3V TBL2301,TPM R3813 TPM C3806 DNP,TPM C3805 cap\_0201\_14mil NC6 SERIRQ 26 LAD0 GND4 VDD4 LAD1 LFRAME# LCLK LAD2 VDD3 GND2 19 VDD3 GND2 17 LAD3 LRESET2# NC9 28 27 26 25 24 TPM\_NC6 1 NC7 2 NC1 NC2 4 GND3 VDD1 6 GPIO 7 PP 9 NC8 10 LRESET1# VDD2 11 NC3 13 NC3 14 NC4 NC5 $\frac{1}{2}$ NC7 4.99K RES\_0201\_12mil 0.1u 6.3V =0.1u 6.3V PCH\_SERIRQ [21,36] LAD0 [21,36] = 0.1u 6.3V == 0.1u 6.3V cap\_0201\_14mil GND 를 GND GND LAD1 [21,36] LFRAME# [21,36] TPM\_PP ← CK\_24M\_TPM [21] TBL2301,TPM **≪≫** LAD2 [21,36] R3814 RES\_0201\_12mil -≪≫ LAD3 [21,36] PLT\_RST#\_BUF [18,22,36,43,75] NC9 GND 는 GND X912460-001 GND TPM\_NC9 R3818 0 PM\_CLKRUN# [21,36] TBL2301,TPM DNP,TPM DNP,TPM C3804 = 22PF 25V R3816 C3807 0 RES\_0201\_12mil 10p 50V CAP\_0201\_14mil CAP\_0201\_14mil GND GND GND Title: TPM Engineer: Surface Microsoft Size Project Name В U -- EV 1.90 1.90.2 Vinafix.com
























































































Title: SI Coupon (was BOOST/GTX REG)

Microsoft Engineer: Surface

Size Project Name
B U -- EV 1.90

Date: Monday, May 11, 2015 Sheet 69 of 76

Vinafix.com

