TECHNICAL NOTE EDITION ANGLAISE



77 11 299 642 **DECEMBER 2000**

C06

XB0



S/Section

Twingo Clio

Type 8 17

17 F L

CORRECTIONS TO THE LABELLING ON THE INJECTION WIRING DIAGRAM

• Engine: D7F 702 and 726 OBD

Basic manuals:

Technical Notes 3056A and 3339A

K4J 712 Gearbox: JB

Correct the name of component 147 on page 17-18 of Technical Note 3056A concerning the Twingo and Clio (D7F).

Correct the name of component 147 on page 17-11 of Technical Note 3339A concerning the Clio (K4J).

The code for component 147 corresponds to the manifold pressure sensor and not the air temperature sensor.