TECHNICAL NOTE EDITION ANGLAISE



77 11 310 122 Edition 2 - NOVEMBER 2003



Type S/Section

X06

X

85A


Twingo

85A

FRONT WIPER MOTOR

Engine: XXXGearbox: XXX

Due to modifications to the front wiper motor, it is now necessary to remove section (A) of the mounting when replacing the motor.



[&]quot;The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.