Alliance Airlines Accident Records: Outcomes

Accident 1: Alliance Airlines Flight 764 (Accident ID: 1)

Outcome: The crew declared an emergency and returned to Brisbane for a successful landing.

There were no injuries among the passengers and crew. The investigation revealed that the

hydraulic system failure was due to a rupture in one of the hydraulic lines. Maintenance protocols

were updated to prevent similar incidents in the future.

Accident 2: Alliance Airlines Flight 850 (Accident ID: 2)

Outcome: The crew executed a safe landing at Perth Airport. The engine was shut down as a

precaution, and there were no injuries. The damaged engine was replaced, and the aircraft was

returned to service after thorough inspections. Bird strike mitigation measures were reviewed and

enhanced at the airport.

Accident 3: Alliance Airlines Flight 982 (Accident ID: 3)

Outcome: The aircraft landed safely, and the injured passengers received medical attention upon

landing. The turbulence incident highlighted the importance of seatbelt use during all phases of

flight. The airline conducted a review of turbulence response procedures and passenger safety

briefings.