IS26 – sensor H4 dashed line: +/-5% for amplitude, +/- 5 degrees for phase Amplitude [dB] 0 IMS passband Phase [deg] 20 frequency [Hz]