

APQP TEAM — RACI RESPONSIBILITY MATRIX

R = Responsible | A = Accountable | C = Consulted | I = Informed | — = Not Involved | Quality Head Agents — QMOS

R Responsible Does the work A Accountable Final authority, owns the outcome C Consulted Asked for input I Informed Kept up to date									
APQP ACTIVITY	Mgr Prog	Eng Design	Eng Mfg	Eng Quality	Mgr Quality	QE Suppl	Procurement	Supv Prod	Head Plant
VOC & Requirements	A	C	C	C	C	C	I	-	I
Design Goals & BOM	A	R	C	C	C	C	C	-	I
APQP Timing Plan	R	I	I	C	C	-	-	-	A
DFMEA	I	R	C	C	A	-	-	-	I
DVP&R	I	R	I	C	A	-	-	-	I
Engineering Drawings	I	R	C	C	A	-	C	-	I
Feasibility Commitment	R	C	C	C	C	C	C	-	A
Process Flow Diagram	I	C	R	C	A	-	-	C	I
PFMEA	I	C	R	C	A	-	-	C	I
Pre-Launch Control Plan	I	C	C	R	A	-	-	C	I
Work Instructions	I	C	R	C	A	-	-	C	I
MSA / GRR Study	I	-	C	R	A	-	-	-	I
Production Trial Run	C	C	R	C	A	C	-	R	I
Cpk / Capability Study	I	-	C	R	A	-	-	C	I
PPAP Submission	C	C	C	C	A	C	-	-	I
Production Control Plan	I	-	C	R	A	-	-	C	I
Gate Reviews	R	C	C	C	C	-	-	-	A
Lessons Learned	R	C	C	C	A	C	C	C	I