

CAPA QUICK REFERENCE GUIDE

IATF 16949 Cl.10.2 | Problem Solving | Root Cause Elimination | QMOS

When to Raise a CAPA

- o Customer complaint or field return
- o Internal NCR - recurring or high severity
- o Audit major nonconformance
- o Management review action item

Root Cause Tools

- o 5-Why Analysis - drill to true system root cause
- o Fishbone (Ishikawa) - 6M: Man, Machine, Material, Method, Env, Measurement
- o Is/Is-Not Analysis - boundary the problem precisely

Effectiveness Criteria

- o Same defect does not recur for 90 days minimum
- o Updated PFMEA, Control Plan, WI reviewed and approved
- o Operators retrained and assessment passed
- o Poka-yoke device verified and documented