

Control Plan - AIAG First Edition Complete Guide

All Columns Explained | Quality Head Agents

Column 1-4: Identification

Process Step No.: Sequential number matching PFD. Process Name/Operation: Name of the manufacturing step (e.g. Welding, Heat Treatment). Machine/Device/Jig: Specific equipment ID or name. Characteristic No.: Sequential number within the CP for traceability.

Column 5-6: Characteristics

Product or Process Characteristic: Product = what the customer measures (dimension, hardness). Process = what the process controls (temperature, speed, pressure). Special Char Class: Mark CC or SC using customer-required symbol. Specification/Tolerance: Exact value from engineering drawing or process spec.

Column 7-9: Measurement

Evaluation/Gauge: Name and ID of the measuring device (CMM-01, Air Gauge AG-02). Must reference calibrated gauge. Sample Size: Specific number (e.g. 5 pieces) - not "as required". Frequency: Specific time or event (e.g. every 25th piece, each shift start, 100%).

Column 10: Control Method

How is the characteristic controlled and monitored? Examples: SPC X-bar R chart, 100% visual, attribute gauge, go/no-go gauge, CMM report, press monitor. Must specify the monitoring system, not just "check".

Column 11: Reaction Plan

What happens when the control signals a problem? Must be specific: Stop machine, segregate since last good piece, 100% sort, notify QA Manager, raise NCR. Never write "inspect further" or "rework if possible" - these are not reaction plans.

Column 12-13: Responsibility and Records

Resp.: Name of role responsible for the control (Operator, QA, Maintenance). Record: Name of the form or system where control results are recorded (SPC chart, inspection log, CMM report, ERP system).