

Control Plan - Common Audit Nonconformities

Major NC & Minor NC Examples | Quality Head Agents

Major NC Examples

1. CC characteristic controlled by sample inspection only (no poka-yoke or 100%) - Clause 8.5.1.1. 2. Control Plan not updated after engineering or process change - Clause 8.5.6.1. 3. CP process steps not matching PFD - broken three-way linkage. 4. No reaction plan or reaction plan says "inspect/rework" (not specific). 5. CP not reviewed and approved before PPAP submission. 6. Customer complaints not reflected in updated CP detection methods.

Minor NC Examples

1. Sample size written as "as required" not a specific number. 2. Control method vague - "check" without specifying gauge or method. 3. Responsible person column blank. 4. Record column blank - no form or system specified. 5. CC/SC column blank when drawing has special characteristic symbols. 6. CP revision date older than 1 year with no review evidence.

Objective Evidence Required

1. Signed Control Plan with revision history. 2. Evidence of annual layout inspection results. 3. Gauge calibration records for all listed gauges. 4. SPC charts for SPC-controlled characteristics. 5. Work Instructions referenced in CP. 6. Link between PFMEA and CP process steps. 7. Training records for operators on reaction plans.

Top Auditor Questions

1. Show me how this CC characteristic is being controlled - 100% or poka-yoke? 2. What would the operator do if this characteristic went out of spec? 3. When was this CP last updated - show me revision history? 4. Show me the link between this CP row and the PFMEA. 5. Show me the gauge used and its calibration certificate.