

Control Plan Reference Posters - Factory Display

A3 Print Ready | Quality Head Agents

Poster 1: Control Plan 13 Columns Quick Reference (A3)

Column 1: Process Step No. | Column 2: Process Name | Column 3: Machine/Jig | Column 4: Char No. | Column 5: Product/Process Char. | Column 6: Spec/Tolerance | Column 7: Gauge/Method | Column 8: Sample Size | Column 9: Frequency | Column 10: Control Method | Column 11: Reaction Plan | Column 12: Responsible | Column 13: Record

Poster 2: CC vs SC vs Standard - Quick Reference (A3)

CC (Critical): Safety impact - 100% inspection or poka-yoke MANDATORY. SPC required. Inverted delta symbol on drawing. SC (Significant): Customer satisfaction - specific inspection frequency. SPC recommended. Special symbol on drawing. Standard: Normal quality - standard sample plan and control method. No special symbol.

Poster 3: 10 Common CP Mistakes (A3)

1. CC without 100% control. 2. Vague reaction plan. 3. Sample size not specified. 4. No gauge reference. 5. CP not linked to PFMEA. 6. Not updated after changes. 7. No work instruction reference. 8. Record column blank. 9. No annual review evidence. 10. Reaction plan not practiced by operators.

Poster 4: Reaction Plan 5-Step Process (A3)

Step 1: STOP - Stop the process immediately. Step 2: SEGREGATE - Quarantine all suspect material (since last good). Step 3: CONTAIN - 100% sort/inspect the segregated material. Step 4: NOTIFY - Inform QA and management as per escalation matrix. Step 5: CORRECT & RECORD - Fix root cause and record all actions in NCR/log.