

Poster 1: PFMEA 7-Step Process (A3)

Step 1: Project Identification - Define scope, team, timing. Step 2: Structure Analysis - Map process steps from PFD. Step 3: Function Analysis - What must each step do? Step 4: Failure Analysis - What can go wrong, what effect, what cause? Step 5: Risk Analysis - Rate S/O/D, calculate AP. Step 6: Optimization - Plan and implement actions for H AP. Step 7: Results - Document, verify, close.

Poster 2: AP Rating Quick Reference (A3)

HIGH (H): S=9-10, OR O=4-5, OR D=1. Action: MANDATORY - Escalate to management. Evidence required. 0-30 days. MEDIUM (M): S=5-8, OR O=2-3, AND D=2-3. Action: REQUIRED - Plan and implement. 30-90 days. LOW (L): All other combinations. Action: REVIEW - Engineer discretion. Next PFMEA review.

Poster 3: PFMEA-Control Plan Link (A3)

Process Step (from PFD) maps to PFMEA row. PFMEA Failure Mode maps to Control Plan check. PFMEA Detection Control maps to Control Plan method. PFMEA Special Characteristics maps to Control Plan CC/SC column. Control Plan Reaction Plan links back to PFMEA corrective action.

Poster 4: 10 Common PFMEA Mistakes (A3)

1. Vague failure mode descriptions. 2. Effect = cause confusion. 3. Detection control = prevention control mix-up. 4. AP=H items not actioned. 5. PFMEA not linked to Control Plan. 6. Not updated after customer complaints. 7. No cross-functional sign-off. 8. Rating done alone (not as team). 9. Special characteristics missed. 10. No revision history maintained.