

PPAP SUBMISSION LEVEL MATRIX

Which Elements Must Be Submitted for Each Level | AIAG PPAP 4th Edition

El#	Element Name	Level 1	Level 2	Level 3 (DEFAULT)	Level 4	Level 5
1	Design Records	R	R	R	R	R
2	Engineering Change Docs	NR	R	R	R	R
3	Customer Eng. Approval	S	R	R	R	R
4	DFMEA	R	R	R	R	R
5	Process Flow Diagram	R	R	R	R	R
6	Process FMEA	R	R	R	R	R
7	Control Plan	R	R	R	R	R
8	MSA Study Results	R	R	R	R	R
9	Dimensional Results	S	R	R	R	R
10	Material/Perf Test Results	S	R	R	R	R
11	Initial Process Capability	S	R	R	R	R
12	Qualified Lab Documentation	R	R	R	R	R
13	AAR	R	R	R	R	R
14	Sample Product	NR	S	S	S	S
15	Master Sample	NR	NR	R	R	R
16	Checking Aids	NR	NR	R	R	R
17	Customer-Specific Req.	R	R	R	R	R
18	PSW (Part Submission Warrant)	S	S	S	S	S

R = Retain at supplier

S = Submit to customer

NR = Not Required at this level

Level 3 = DEFAULT (most common)