

RE-PPAP TRIGGER REFERENCE GUIDE

12 Conditions Requiring Re-PPAP | AIAG PPAP 4th Edition Section 3 | IATF 16949 Clause 8.3.6

MANDATORY RE-PPAP TRIGGERS — ANY OF THESE = NEW PPAP REQUIRED

#	Trigger Condition	Risk	Timing
1	New part or product (no prior PPAP approved)	High	Immediate
2	Correction of discrepancy on a previously submitted part	High	Before next shipment
3	Engineering change to design records, specifications, or materials	High	Before shipping changed parts
4	Change in manufacturing site (new plant, building, or line)	High	Before first production shipment
5	Production after tooling inactive ≥ 12 months	Medium	Before restart shipment
6	Transfer of tooling or equipment to different machine, location, or supplier	High	Before resuming production
7	Change in sub-supplier for materials or services affecting fit/form/function	Medium	Within agreed timeline
8	Change in manufacturing method (new process, new technology)	High	Before production
9	Change in inspection/test method with new acceptance criteria	Medium	Before next audit cycle
10	New or modified tools (excluding normal maintenance)	Medium	Before first production shipment
11	Product not produced for customer within 12 months (bulk = 12 months)	Medium	Before restart shipment
12	Customer specifically requests Re-PPAP	High	Per customer timeline

■ When in doubt, always contact your customer SQE before making any change. Unauthorized changes that affect fit, form, or function without Re-PPAP can result in warranty claims, line stoppage penalties, and disqualification as an approved supplier.