

SPC Competency Matrix - Roles and Required Knowledge Levels

L1=Awareness, L2=Practitioner, L3=Expert | AIAG SPC 2nd Edition

QUALITY HEAD AGENTS | AIAG SPC 2nd Edition | IATF 16949:2016

Competency Matrix by Role

Quality Head:	L3 - Control Charts L3 - Cpk/Ppk L3 - Nelson Rules L3 - IATF Audit L3 - PPAP Element 9
Quality Manager:	L3 - Control Charts L3 - Cpk/Ppk L2 - Nelson Rules L2 - IATF Audit L3 - PPAP Element 9
Quality Engineer:	L2 - Control Charts L2 - Cpk/Ppk L2 - Nelson Rules L2 - IATF Audit L2 - PPAP Element 9
SPC Operator:	L1 - Control Charts L1 - Cpk/Ppk L1 - Nelson Rules L1 - Reaction Plan - PPAP
Production Supervisor:	L1 - Control Charts L1 - Cpk/Ppk L1 - Nelson Rules L1 - Reaction Plan - PPAP

Evaluation Methods

Level 1 - Test:	15-question multiple choice. Practical: correctly plot 5 readings and identify Rule 1. Pass: 80%.
Level 2 - Test:	30 questions including capability calculations. Practical: calculate Cpk from data set, interpret result. Pass: 75%.
Level 3 - Assessment:	IATF audit simulation (10 questions). Practical: review a real control chart, identify all signals, present improvement plan. Pass: 80%.
Retraining Required:	After audit NC on SPC, when operator Cpk deteriorates, after new chart type introduced, annually for all SPC operators.