Inspection Engineers, Inc.

6135 NW 167th Street, Suite E28
Hialeah, Florida 33015
Phone: (305) 232-8691
Email: InspectionEngineersInc@gmail.com
Website: www.InspectionEngineersInc.com

I.E.

January 23, 2025

Turnberry on the Green Condominium Association
19501 W. Country Club Drive
Aventura, FL 33180

Attn: Mr. Carlos Serrano
Phone: (305) 978-0971
Email: serranoc@kwpmc.com

Re: Structural inspections proposal for the garage repairs

Dear Board members,

Thank you for contacting our company, Inspection Engineers, Inc., to assist you with the repairs needed in the garage of your building. Following is our proposed scope of work:

1. Review the existing structural drawings of the specific area that presents structural damage.
2. Perform a structural inspection and a take-off in order to be able to assess the damage and to provide a detail drawing to stop the settlement in the affected area.
3. Provide specifications for the repairs.
4. Provide 3 to 4 inspections once the contractor is selected for the repair.

We will assign one structural engineer (threshold) in order to perform the inspection and detailed drawing. The time needed is two weeks.

The fee is $4,800 payable 50% at signing and the balance at the delivery of the documents. The supervision inspections will be charged at $650 each and will be coordinated with management and the contractor.

Please countersign if are in agreement and issue a check for $2,400 to initiate our inspections.

Sincerely,

Douglas H. Mercado
President

Approved: _____ Date: 04-28-2025
Turnberry on the Green Condominium Association