Thermistor String Worksheet

Originator (Sales Team)	Customer Name	Sales Order #	SME Approval

- What **Model** of thermistor string is required?
- 2. What is the overall **String Length**? (see Figure) **Measurement units**: \square Meters \square Feet
- 3. Indicate Distance from Sensor 1 to each additional Sensor (temperature measurement location):

Sensor	D, Distance		Sensor	D, Distance
1	0		17	
2	0.25		18	
3	0.25		19	
4	0.25		20	
5	0.25		21	
6	0.25		22	
7	0.25		23	
8			24	
9			25	
10			26	
11			27	
12			28	
13			29	
14			30	
15			31	
16			32	
		ı		




Figure - Thermistor String

Notes:

- D2 = Distance from Sensor 1 to Sensor 2
- D3 = Distance from Sensor 1 to Sensor 3
- Etc.

Other comments:

8032-27 Jumpers required:

Jumpers are required to connect the common conductor to a datalogger or Mulitiplexer. One jumper is required for every 6 temperature measurement points. One extra jumper is required if # points is greater than 6.

Example: 15 sensors = 4 jumpers required (1 for 1^{st} 6 points, 1 for 2^{nd} 6, 1 for remaining 3, 1 extra since # points >6)



File name: Thermistor String Rev D.docx Rev: D