

Heart Rate & Pulse Oximeter Sensor Haptic Motor Driver U1 MAX30102EFD+T U2 DRV2605LYZFR +3V3 +1V8 +VBAT C1 SCL SDA SCL SDA VLED+ ± C6 VLED+ B1 IN/TRIG → 100n ± 100n 4u7 R1 10k IR_DRV REG A2 REG R_DRV GND GND 1u PGND GND GND GND GND GND Mezzanine Connector Input & Battery Pads J1 AXG220144 +VBAT VBUS +3V3 [≤] TP1 TP3 1.5mm 1.5mm TP2 ⊕ VBUS ≤ TPD1E10B06DPYR 1.5mm +VBAT ←







Sheet: / File: watch_lower.kicad_sch Title: Size: A4 Date: KiCad E.D.A. kicad 7.0.1 ld: 1/1