

Temperature Conversion Chart

°C	°F	°C	°F	°C	°F	°C	°F	°C	°F	°C	°F
-270	-454	16	60.8	61	141.8	160	320	610	1130	1120	2048
-280	-472	17	62.6	62	143.6	170	338	620	1148	1140	2084
-270	-454	18	64.4	63	145.4	180	356	630	1166	1160	2120
-260	-436	19	66.2	64	147.2	190	374	640	1184	1180	2156
-250	-418	20	68	65	149	200	392	650	1202	1200	2192
-240	-400	21	69.8	66	150.8	210	410	660	1220	1220	2228
-230	-382	22	71.6	67	152.6	220	428	670	1238	1240	2264
-220	-364	23	73.4	68	154.4	230	446	680	1256	1260	2300
-210	-346	24	75.2	69	156.2	240	464	690	1274	1280	2336
-200	-328	25	77	70	158	250	482	700	1292	1300	2372
-190	-310	26	78.8	71	159.8	260	500	710	1310	1350	2462
-180	-292	27	80.6	72	161.6	270	518	720	1328	1400	2552
-170	-274	28	82.4	73	163.4	280	536	730	1346	1450	2642
-160	-256	29	84.2	74	165.2	290	554	740	1364	1500	2732
-150	-238	30	86	75	167	300	572	750	1382	1550	2822
-140	-220	31	87.8	76	168.8	310	590	760	1400	1600	2912
-130	-202	32	89.6	77	170.6	320	608	770	1418	1650	3002
-120	-184	33	91.4	78	172.4	330	626	780	1436	1700	3092
-110	-166	34	93.2	79	174.2	340	644	790	1454	1750	3182
-100	-148	35	95	80	176	350	662	800	1472	1800	3272
-90	-130	36	96.8	81	177.8	360	680	810	1490	1850	3362
-80	-112	37	98.6	82	179.6	370	698	820	1508	1900	3452
-70	-94	38	100.4	83	181.4	380	716	830	1526	1950	3542
-60	-76	39	102.2	84	183.2	390	734	840	1544	2000	3632
-50	-58	40	104	85	185	400	752	850	1562	2050	3722
-40	-40	41	105.8	86	186.8	410	770	860	1580	2100	3812
-30	-22	42	107.6	87	188.6	420	788	870	1598	2150	3902
-20	-4	43	109.4	88	190.4	430	806	880	1616	2200	3992
-10	14	44	111.2	89	192.2	440	824	890	1634	2250	4082
0	32	45	113	90	194	450	842	900	1652	2300	4172
1	33.8	46	114.8	91	195.8	460	860	910	1670	2350	4262
2	35.6	47	116.6	92	197.6	470	878	920	1688	2400	4352
3	37.4	48	118.4	93	199.4	480	896	930	1706	2450	4442
4	39.2	49	120.2	94	201.2	490	914	940	1724	2500	4532
5	41	50	122	95	203	500	932	950	1742	2550	4622
6	42.8	51	123.8	96	204.8	510	950	960	1760	2600	4712
7	44.6	52	125.6	97	206.6	520	968	970	1778	2650	4802
8	46.4	53	127.4	98	208.4	530	986	980	1796	2700	4892
9	48.2	54	129.2	99	210.2	540	1004	990	1814	2750	4982
10	50	55	131	100	212	550	1022	1000	1832	2800	5072
11	51.8	56	132.8	110	230	560	1040	1020	1868	2850	5162
12	53.6	57	134.6	120	248	570	1058	1040	1904	2900	5252
13	55.4	58	136.4	130	266	580	1076	1060	1940	2950	5342
14	57.2	59	138.2	140	284	590	1094	1080	1976	3000	5432
15	59	60	140	150	302	600	1112	1100	2012	3050	5522

Conversion Equations