## Given:

- . fuel enrichment 3.5 /.
- . thermal neutron plux -> 2.8 × 1013 n/cm2.s

## : soifqmuzz A

- . Neplipible contribution from U238, Pu239, etc.  $N_f \approx N_f^{35} = 550 \, b = 5.5 \times 10^{22} \, cm$
- . 95 / of the energy released from fission is converted to heart > Ef=0.95(200 NeV/fission)=190 MeV/fission

  or

  =3×1011/pission

$$3 \times 10^{13} \text{ J/s}$$
  $5.5 \times 10^{22}$   $2.8 \times 10^{13} \text{ Alon2.}$ 

$$O[W/cm^{3}] = Ef[N_{f}^{35}] \sqrt{5_{f}^{35}} \sqrt{9_{+h}}$$
 where  $N_{f}^{35} = 0.035 \text{ Nu}$ 

We need to calculate Nu por each material as pollows:

$$Nu = \frac{\rho_u^* N_A}{Mu}$$
 where  $\rho_u^*$  is uranium density in the given marterial.  
 $Mu = (0.035) 235 + (1-0.035) 238 = 237.9 g/max$ 

$$\frac{Pu^{\frac{1}{2}}}{Nu} = \frac{Nu^{\frac{1}{2}} \times 10^{24} \text{ atomilian}}{237.9} = 0.035 Nu \left[ \text{atomilian} \right] \frac{D[W/n^{\frac{3}{2}}]}{237.9}$$

$$\frac{Nu^{\frac{1}{2}} = 0.035 Nu \left[ \text{atomilian} \right]}{255 \times 10^{20}} = 0.0244 \longrightarrow 9.55 \times 10^{20}$$

metal 
$$\rightarrow$$
  $\frac{\ln N_A}{\rho u l} = \frac{(19.04)(0.6022)}{237.9} = 0.0482 \rightarrow 1.69 \times 10^{21}$  ~ 779

$$\frac{|uC|}{|Mu|} = \frac{(12.97)(0.6022)}{237.9} = 0.0328 - 3 (15 \times 10^{21})$$

$$\frac{\text{(a) N_A}}{\text{My}} = \frac{(13.52)(0.6022)}{237.9} = 0.0342 \longrightarrow 1.20 \times 10^{21}$$


$$U_3 Si_2 \rightarrow \frac{(U_3 Si_2 NA)}{Mu} = \frac{(11.31)(0.6022)}{2.37.7} = 0.0286 \rightarrow 1 \times 10^{21}$$


- a) Main fissile atom fissioned in my reactor will primarily be U235. exists in pud and Pu239 which will be penerated from U238 by neutron absorption.
  - b) UO2 will be used due to its high melting temperature, thermal stability due to its seramic form, relatively good corrasion resistance which is crucial in terms of safety existence of relatively more experience on its behavior in normal operation or transient.
  - c) Coolant will be used to remove the heat penerated in the fuel to keep its temperature below the limits enabling us safe reactor operation. Super critical water will be used due to its very high heat capacity. Working with such coolant can provide additional safety feature in Such a way that it does not boil in case of loss of coolant.
    - d) Reactor codout can be increased as much as desired due to the lack of phase charge.

      High heat will primarily be used for hydrogen peneration. This approach is expected to be more profitable in long term compared with electricity production.

      by considering the limited amount of natural resources.
  - e) Thermal neutrons will be used. Since the density of the coolant is expected to be very (ow, it is necessary to use additional moderator (Be, H2O, D2O etc.) having relatively higher density.
  - f) Fuel consists of UD2 pellets with cladding similar to LURS. However, stainless steel will be used due to its high temperature corrosion resistance. Fuel geometry will be sylindrical similar to LURS parming NXN square fuel assembly. Unlike typical LURS, addition channels will be added for the moderator to flow.

Once-through cycle is considered; spent fuels are removed and stored in the spent fuel pool for its activity to reduce. After the vitrification, vitrified fuels will be stored in dry storage cashs.





- 1) Mining: Natural uranium with 0.7% is mined in UO2 form and sent for milling.
- 2) Milling: Mined UD2 is milled to a pine powder. Yellow cake in U308 is parmed after a series of chemical processing
- 3) Conversion: UsO8 yellow cake is converted into UFE (07%) for enrichment process. Conversion to UFE is essected since it is in gas form at room temperature.
- 4) Enrichment: UF6 (0.7 1.) is enriched to UF6 (3-4.1.) with a series of successive enrichment steps. Enrichment can be done by using; pass diffusion technique, poss centriques technique or laser extraction. Most common one is either pass diffusion or pas centriques. In these techniques, UF6 enrichment is increased step by step to 3-41. During this process, large amount of energy is consumed. Such energy is provided from additional power plants which are generally constructed next to the enrichment facility.
- Fuel forbrication: 3-4% enriched UFG is converted to powder UD2 with a desired stoichiometry.

  Pellets are then formed and sintered to get seramic form with a desired grain size for best performance. Due to the thermal expossion during the reactor aperolian, these pellets are champered on the shoulders and dimpled at the center to keep integrity of the fuel cladding as much as possible