


Construction Manual



Welcome to the FLipMouse

Construction Manual

This manual covers detailed step-by-step instructions for building the FLipMouse alternative input system.

As additional tools you will need:

- a soldering iron with a fine tip
- sharp side-cutting pliers
- a PH/PZ screwdriver (PH0 or PH1)
- optionally a PCB holder

The required materials are:

- tin-solder (small diameter)

Legend



Solder / do not solder

Clip / do not clip with pliers



Attention: orientation of this part is important!



This part is done in this step



Parts necessary for this step
(see part overview on page 3/4)




Step number for reference

Part Overview - Electronic Parts


1



2



3




4




Part Overview - Case Parts


5




6



8




9




10



11



12



13







14



1

2






1

3

5

6

7





2

5



8

9




3

10 11







4




6



5







6



7



4



7

12

13



2x







8

8

14



9



Copyright 2023, AsTeRICS Foundation, CC-BY-SA 3.0
office@asterics-foundation.org

Acknowledgements:

Futura fonts by www.onlinewebfonts.com (CC BY 3.0)

Exclamation mark icon made by Pixel Buddha from www.flaticon.com

Illustrations based on work of Moritz Schwarzl (moritz.schwarzl@gmx.at)