$$2M_{A=0}$$
, $-12(3) *6(3) *9(6) + Fog(a) = 0$
 $Fog = 12$
 $2F_{g} = 0$, $FA_{g} = 3$
 $2F_{x} = 0$, $FA_{x} = \bullet -12$

Point E