

SOP-CELL-014 Gripper finger set change

Procedure: SOP-CELL-014

Revision: A

Work record

Work order: WO-26-0391

Machine: ARM-3A

Performed on: 2026-08-18

Diagnosis: Finger pads worn beyond limit; set replaced with the long set

Procedure

- Stop the cell and lock out the controller
- Release the gripper and remove the two finger retaining screws
- Fit the new finger set and torque the screws to 2.5 N.m
- Update the tool centre point and run the part-present check

Parts replaced

Part	Removed	Installed
Finger set PG-80	FS-0183	FS-0291
Retaining screw set	SCR-KIT-77	SCR-KIT-81
Performed by: K. Patel		