




Switch must be MBB timing to avoid MCU reset (make before break also known as shorting)







SPI FLASH




KH25L6408E = 8 MByte version




CAP SENSE



POWER



LEDs



AUDIO

