```
// Project 12 - Pulse Monitor Test Script
int ledPin = 13;
int sensorPin = 0;
double alpha = 0.75;
int period = 20;
double change = 0.0;
void setup()
{
 pinMode(ledPin, OUTPUT);
 Serial.begin(115200);
}
void loop()
{
  static double oldValue = 0;
  static double oldChange = 0;
  int rawValue = analogRead(sensorPin);
  double value = alpha * oldValue + (1 - alpha) * rawValue;
  Serial.print(rawValue);
  Serial.print(",");
  Serial.println(value);
  oldValue = value;
  delay(period);
}
```

This article was published on Monday 09 January, 2012.