

PHASE 6

ROLES, TIMING & KEY CONTROLS REFERENCE

Quick-reference for operators, supervisors, and downstream teams

- App Checkpoint
- Critical Control
- Manual/Inferred
- Decision
- Handoff

ROLE ASSIGNMENTS BY PHASE

Phase	Primary Role	Secondary Role	Support
Phase 1 — Charge & Primary	Extractor (EXT)	Supervisor if exception	Maintenance if needed
Phase 2 — Flush & Purge	Extractor (EXT)	Supervisor if out of range	—
Phase 3 — Shutdown	Extractor (EXT)	—	—
Phase 4 — Pour & Handoff	Extractor (EXT)	Downstream Operator (DOWN)	—

TIMING TARGETS

Step	Target	Notes
Primary Soak	30 minutes	Settings-driven; timing misses can warn or hard-stop
Mixer / Agitation	5 minutes	Timed separately within primary soak window
Flush Soak	10 minutes	Settings-driven; stores flush count and total weight
Final Purge	Optional	Target duration configurable in Settings
Post-Extraction Start	Immediate	Blocked until run is marked complete

CRITICAL CONTROLS — MUST NOT BE SKIPPED

- C1

Lot Readiness Check

Correct lot, available weight, and charge eligibility must be confirmed before any biomass is committed to a reactor.
- C2

Vacuum Down Confirmation

Must be confirmed via app button before solvent charge can proceed. No exceptions — hard prerequisite.
- C3

Solvent Chiller Temperature

Must be at or below −40 °F before flush solvent charge. Photo evidence upload supported; app is the stronger system record.
- C4

Basket Filter Clear

Must be confirmed before nitrogen pressurization begins. Critical safety checkpoint in the pressurization sequence.
- C5

Shutdown Checklist (4 items)

All four items must be captured before run complete:
Recovery inlets closed · Filtration pump-down · Nitrogen off · Dewax inlet closed
- C6

Dual Wet Output Weights

Both Wet HTE and Wet THCA gram values must be entered before Confirm Initial Outputs can be pressed.