

PHASE 7

PROCESS GAPS & SUGGESTED IMPROVEMENTS

Identified gaps and recommendations from the SOP alignment review

- App Checkpoint
- Critical Control
- Manual/Inferred
- Decision
- Handoff

SUGGESTED ADDITIONS

- S1

Run Card

Add a one-page laminated "Run Card" with the same step numbers as the app buttons for quick operator reference at the booth.
- S2

Phase Grouping

Group the tablet workflow into four big phases:
Charge · Primary · Flush/Purge · Pour/Handoff
- S3

Visual Progress Rail

Add a visual progress rail on-screen showing Branch A/B and Branch C/D loops directly so operators can track state.
- S4

Prep & Cleaning Visibility

Make preparation and cleaning steps visible in the app:
Reactor ready · Solvent tank ready · Containers labeled · Post-run reset
- S5

Role Initials on Steps

Display role initials on each step in the app:
EXT (Extractor) · SUP (Supervisor) · DOWN (Downstream) · MAINT (Maintenance)

PROCESS GAPS — CONFIRM WITH TEAM

- G1

Cleaning & Readiness Ownership

Exact owner and timing for tank cleaning, solvent loading, and reactor readiness checks are not fully defined.
- G2

Temperature Hard Stop Policy

Confirm whether −40 °F is a hard stop or a supervisor-overridable warning in production settings.
- G3

Evidence Source of Truth

Confirm whether Slack evidence remains required or whether app photo evidence fully replaces it as the system record.
- G4

Output Container Requirements

Confirm whether wet HTE and wet THCA require container labels, tare weights, photos, or supervisor sign-off.
- G5

Run Complete Definition

Confirm whether "run complete" means booth shutdown complete or wet output pour complete — these differ operationally.