
How to Read Motor Datasheets

Modularcircuits.com/blog/articles/bridge-to-the-far-side/how-to-read-motor-datasheets/



Introduction

This short article builds on the work we've done in modeling DC motors. Here I'll show you how to turn that knowledge into practice and at the same time, extract useful information from motor datasheets.

The reason you'll have to do that exercise is that most motor manufacturers usually specify only a few things on their datasheets. Here are a few examples:

http://www.kysanelectronics.com/Products/SubClass.php?recordID=281

http://www.micromo.com/coreless-dc-motors-data-sheets.aspx

Motor operating points and parameters

There are four interesting operating points of a motor, and a manufacturer usually specifies the parameters for at least a few:

- 1. No-load characteristics is measured when there's nothing attached to the shaft of the motor, and is supplied the rated operating voltage
- 2. Stall characteristics is measured when the motor shaft is completely blocked (can't move at all) and the motor is supplied its rated operating voltage note, that to measure actual torque, the shaft needs to move a little bit, and as a result as you will see later friction still plays a role in this operating point
- 3. The maximum efficiency characteristics, again measured with the rated operating voltage supplied
- 4. The maximum power output characteristics, still with the rated operating voltage applied.

The interesting parameters at these for operating points are (using the 's' suffix for 'spec'):

- 1. Speed (s_s)
- 2. Torque (T_s)
- 3. Current (I_s)
- 4. Voltage on the motor terminals (though it's kept constant between all four measurements above) (V_s)

From these, the following parameters can be determined:

- 1. Motor constants (K_T, K_E)
- 2. Motor internal resistance (R_m)
- 3. Motor friction (T_{friction})

To make sense of it all

It is important to understand that all measurements are done in a static condition. This means that reactive elements (the inductance of the coils, L_m or the inertia of the rotor, J_m) don't play a role in the parameters, but it also means that they can't be determined if the datasheet doesn't specify them.

As always, the motor conversion equations are true, and are the same for all operating points:

$$T = K_T*I$$

and
 $V_g = K_E*s$

There are two losses in the motor to consider: the internal resistance (R_m) and the friction ($T_{friction}$). In this discussion we will use the much more accurate (though nonlinear) friction model as opposed to the linear drag model to represent mechanical losses in the motor. That means that the friction torque ($T_{friction}$) is constant as long as the direction of the rotation doesn't change. With the reactive elements out of the way, we know that the current through the motor will drop a constant voltage across the internal resistance and the rest is available for mechanical conversion:

$$V_s = I*R_m + V_g$$

Similarly, some of the torque on the mechanical side is used to compensate for the friction and the rest is available on the shaft of the motor:

$$T_s = T_{converted} - T_{friction}$$

From these, for any of the measurements, we can get the following:

$$T_s + T_{friction} = K_T * I_s$$

$$V_s - I_s R_m = K_F S_s$$

The knowns here are: T_s, s_s, I_s and V_s. We're looking for T_{friction}, R_m, K_T and K_E. If you have

data available from the datasheet for at least two of the four operating points, you can in theory arrive at the unknowns. However, two special cases can help: if you have information on the stall or no-load operating point, a few things get simpler. In both cases, all the energy pumped into the motor on the electrical side is entirely used up on the internal losses: the resistance and the friction.

For the stalled case, the shaft is not rotating, which means that the generator voltage (V_g) must be 0, just as s_s is. The second equation becomes simpler with that knowledge:

$$V_s - I_{s(stall)} R_m = 0$$

From this, R_m can be expressed:

$R_m = V_s/I_{s(stall)}$

For the no-load case, we know that the converted torque is just enough to compensate the friction, there's no torque left on the shaft. So T_s must be 0. Because of that, the first equation becomes:

$$T_{friction} = K_T * I_{s(no-load)}$$

Putting this value for T_{friction} back into the torque equation for the stall-case, we get:

$$T_{s(stall)} + K_T * I_{s(no-load)} = K_T * I_{s(stall)}$$

Now, solving it for K_T, we get:

$K_T = T_{s(stall)}/(I_{s(stall)}-I_{s(no-load)})$

With these two, we can calculate the remaining two parameters ($T_{friction}$ and K_E) for any operating point using our original two equations:

$$T_s + T_{friction} = K_T * I_s$$
 which leads to $T_{friction} = K_T * I_s - T_s$

$$V_s - I_s * R_m = K_E * s_s$$
 which leads to $K_E = (V_s - I_s * R_m) / S_s$

Of course $T_{friction}$ and K_E should be constants, independent of the set of parameters we calculate them from, but it's a good test to calculate them from all possible sources and see how much different the values are.

Let's try it!

I'm going to use my usual motor, the <u>RS-550PF-8021</u>. The datasheet specifies all four operating points, that I'm summarizing in the following table:

	T _s	S _S	V_s	Is
no-load	0 mNm	24000 RPM	12 V	1.5 A

stall	647.25 mNm	0	12 V	148 A
maximum efficiency	58.252 mNm	21840 RPM	12 V	14.685 A
maximum power	323.62 mNm	12000 RPM	12 V	74.75 A

From the stall and no-load numbers, we can get:

 K_T = 4.418 mNm/A and R_m = 81m Ω . (As it turns out the datasheet also specifies these parameters and they in fact match up with our calculations.)

And with that, we can calculate the other two parameters for the operating points:

	$T_{friction}$	K _E
no-load	6.627 mNm	N/A
stall	6.627 mNm	4.726
maximum efficiency	6.632 mNm	4.726
maximum power	6.627 mNm	4.726

The numbers are almost perfectly the same, only the friction shows a less than 0.1% error.

The last parameter specified in the datasheet is actually a typo: it's not he back-EMF constant (K_E), but another parameter of the motor that we haven't talked about yet, K_M . It can be calculated like this:

$$K_M = K_T/sqrt(R_m)$$

You can verify that both the value and the unit works out from the numbers we have so far.

Further reading

To prepare this article, I've used the following papers. They can be a good source for additional information and background.

- http://www.globe-motors.com/dc_motor.pdf
- http://www.micromo.com/Data/Sites/1/technical-librarypdf/dc_motor_calculations.pdf